



# Dorothy Heights ES Lead Water Test Results



## FY18 Filter Test

### Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 008550	6/12/2017	6/12/2018	2	Cooler	In hallway adjacent to room 219	Right Low	WF-62017-008550	11/9/2017	FT-FY18-62017-008550-A	<1	FT-FY18-62017-008550-B	<1
WS- 008554	6/12/2017	6/12/2018	3	Cooler	In hallway adjacent to room 310	Right Low	WF-62017-008554	11/9/2017	FT-FY18-62017-008554-A	<1	FT-FY18-62017-008554-B	<1
WS- 008555	10/18/2017	10/25/2018	1	Classroom Faucet	Annex, in classroom 013		WF-102017-008555	11/9/2017	FT-FY18-102017-008555-A	<1	FT-FY18-102017-008555-B	<1
WS- 008556	10/18/2017	10/25/2018	1	Classroom Faucet	Annex, in classroom 015		WF-102017-008556	11/9/2017	FT-FY18-102017-008556-A	<1	FT-FY18-102017-008556-B	<1
WS- 008592	10/18/2017	10/25/2018	1	Classroom Faucet	Annex, in classroom 012		WF-102017-008592	11/9/2017	FT-FY18-102017-008592-A	<1	FT-FY18-102017-008592-B	<1
WS- 010543	10/18/2017	10/25/2018	1	Classroom Faucet	Annex, in classroom 006		WF-102017-010543	11/9/2017	FT-FY18-102017-010543-A	<1	FT-FY18-102017-010543-B	<1

## Food Prep Sink

### Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008541	1	Food Prep Sink	In kitchen	11/9/2017	FT-FY18-102017-008541-A	<1	FT-FY18-102017-008541-B	<1
WS- 008542	1	Food Prep Sink	In kitchen	11/9/2017	FT-FY18-102017-008542-A	<1	FT-FY18-102017-008542-B	<1