



# Duke Ellington Lead Water Test Results



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009192	8/18/2017	8/18/2018	1	Cooler	In hallway across from electrical room 124a	Left High	WF-82017-009192	12/19/2017	FT-FY18-82017-009192-A	<1	FT-FY18-82017-009192-B	<1
WS- 009405	8/17/2017	8/17/2018	Ground Floor	Cooler	In hallway across from room G60	Right Low	WF-82017-009405	12/19/2017	FT-FY18-82017-009405-A	<1	FT-FY18-82017-009405-B	<1
WS- 009406	8/17/2017	8/17/2018	Ground Floor	Cooler	In cafeteria	Left High	WF-82017-009406	12/19/2017	FT-FY18-82017-009406-A	<1	FT-FY18-82017-009406-B	<1
WS- 009407	8/17/2017	8/17/2018	Ground Floor	Cooler	In cafeteria	Right Low	WF-82017-009407	12/19/2017	FT-FY18-82017-009407-A	<1	FT-FY18-82017-009407-B	<1
WS- 009419	8/17/2017	8/17/2018	Ground Floor	Health Suite	In health suite in alcove G16		WF-82017-009419	12/19/2017	FT-FY18-82017-009419-A	<1	FT-FY18-82017-009419-B	<1
WS- 009425	8/17/2017	8/17/2018	1	Cooler	In hallway adjacent to storage room 131	Right Low	WF-82017-009425	12/19/2017	FT-FY18-82017-009425-A	<1	FT-FY18-82017-009425-B	<1
WS- 009431	8/17/2017	8/17/2018	1	Cooler	In hallway adjacent to storage room 155	Right Low	WF-82017-009431	12/19/2017	FT-FY18-82017-009431-A	<1	FT-FY18-82017-009431-B	<1
WS- 009446	8/17/2017	8/17/2018	1	Break Room	In main office across from office room 119		WF-82017-009446	12/19/2017	FT-FY18-82017-009446-A	<1	FT-FY18-82017-009446-B	<1
WS- 009448	8/17/2017	8/17/2018	2	Cooler	In hallway adjacent to dance studio 218	Right Low	WF-82017-009448	12/19/2017	FT-FY18-82017-009448-A	<1	FT-FY18-82017-009448-B	<1
WS- 009456	8/17/2017	8/17/2018	2	Cooler	In hallway adjacent to LMC studio 245	Right Low	WF-82017-009456	12/19/2017	FT-FY18-82017-009456-A	<1	FT-FY18-82017-009456-B	<1
WS- 009457	8/17/2017	8/17/2018	2	Cooler	In hallway adjacent to classroom 265	Left High	WF-82017-009457	12/19/2017	FT-FY18-82017-009457-A	<1	FT-FY18-82017-009457-B	<1
WS- 009459	8/17/2017	8/17/2018	2	Break Room	In workroom 206		WF-82017-009459	12/19/2017	FT-FY18-82017-009459-A	<1	FT-FY18-82017-009459-B	<1
WS- 009461	8/17/2017	8/17/2018	2	Cooler	In hallway adjacent to classroom 209	Right Low	WF-82017-009461	12/19/2017	FT-FY18-82017-009461-A	<1	FT-FY18-82017-009461-B	<1
WS- 009462	8/17/2017	8/17/2018	3	Cooler	In instrumental studio room 313		WF-82017-009462	12/19/2017	FT-FY18-82017-009462-A	<1	FT-FY18-82017-009462-B	<1
WS- 009468	8/17/2017	8/17/2018	3	Cooler	In orchestra rehearsal room 363		WF-82017-009468	12/19/2017	FT-FY18-82017-009468-A	<1	FT-FY18-82017-009468-B	<1
WS- 009469	8/17/2017	8/17/2018	3	Cooler	In hallway adjacent to classroom 372	Left High	WF-82017-009469	12/19/2017	FT-FY18-82017-009469-A	<1	FT-FY18-82017-009469-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009409	Ground Floor	Food Prep Sink	In kitchen second clockwise from entry door	12/19/2017	FT-FY18-122017-009409-A	<1	FT-FY18-122017-009409-B	<1