



# Dunbar HS Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-005043	6/14/2018	6/14/2019	3	Cooler	In hallway adjacent to room 381	High Left	WF-06142018-005043	1/10/2019	FT-FY19-012019-005043-A	<1	FT-FY19-012019-005043-B	<1
WS-005044	6/14/2018	6/14/2019	3	Cooler	In hallway adjacent to room 381	Low Right	WF-06142018-005044	1/10/2019	FT-FY19-012019-005044-A	<1	FT-FY19-012019-005044-B	<1
WS-005045	6/14/2018	6/14/2019	3	Break Room	In break room 398		WF-06142018-005045	1/10/2019	FT-FY19-012019-005045-A	<1	FT-FY19-012019-005045-B	<1
WS-005088	6/14/2018	6/14/2019	4	Cooler	In hallway adjacent to room 481	High Left	WF-06142018-005088	1/10/2019	FT-FY19-012019-005088-A	<1	FT-FY19-012019-005088-B	<1
WS-005089	6/14/2018	6/14/2019	4	Cooler	In hallway adjacent to room 481	Low Right	WF-06142018-005089	1/10/2019	FT-FY19-012019-005089-A	<1	FT-FY19-012019-005089-B	<1
WS-005090	6/14/2018	6/14/2019	4	Break Room	In break room 498		WF-06142018-005090	1/10/2019	FT-FY19-012019-005090-A	<1	FT-FY19-012019-005090-B	<1
WS-005096	6/14/2018	6/14/2019	1	Break Room	In break room 117		WF-06142018-005096	1/10/2019	FT-FY19-012019-005096-A	<1	FT-FY19-012019-005096-B	<1
WS-009164	6/14/2018	6/14/2019	4	Break Room	In break room 482A		WF-06142018-009164	1/10/2019	FT-FY19-012019-009164-A	<1	FT-FY19-012019-009164-B	<1
WS-009166	6/14/2018	6/14/2019	2	Break Room	In break room in library		WF-06142018-009166	1/10/2019	FT-FY19-012019-009166-A	<1	FT-FY19-012019-009166-B	<1
WS-012258	6/14/2018	6/14/2019	Basement	Cooler	In hallway adjacent to pool/060	Low Right	WF-06142018-012258	1/10/2019	FT-FY19-012019-012258-A	<1	FT-FY19-012019-012258-B	<1
WS-012259	6/14/2018	6/14/2019	Basement	Cooler	In hallway adjacent to pool/060	High Left	WF-06142018-012259	1/10/2019	FT-FY19-012019-012259-A	<1	FT-FY19-012019-012259-B	<1
WS-012260	6/14/2018	6/14/2019	1	Cooler	In hallway adjacent to room 162	High Left	WF-06142018-012260	1/10/2019	FT-FY19-012019-012260-A	<1	FT-FY19-012019-012260-B	<1
WS-012261	6/14/2018	6/14/2019	1	Cooler	In hallway adjacent to room 162	Low Right	WF-06142018-012261	1/10/2019	FT-FY19-012019-012261-A	<1	FT-FY19-012019-012261-B	<1
WS-012264	6/14/2018	6/14/2019	1	Classroom Faucet	In athletics training room 153		WF-06142018-012264	1/10/2019	FT-FY19-012019-012264-A	<1	FT-FY19-012019-012264-B	<1
WS-012265	1/2/2019	1/2/2020	1	Food Prep Sink	In kitchen first clockwise from entry door		WF-01022019-012265	1/10/2019	FT-FY19-012019-012265-A	<1	FT-FY19-012019-012265-B	<1
WS-012273	6/14/2018	6/14/2019	1	Break Room	In break room 198		WF-06142018-012273	1/10/2019	FT-FY19-012019-012273-A	<1	FT-FY19-012019-012273-B	<1
WS-012275	6/14/2018	6/14/2019	1	Cooler	In hallway adjacent to room 197	Low Right	WF-06142018-012275	1/10/2019	FT-FY19-012019-012275-A	<1	FT-FY19-012019-012275-B	<1
WS-012321	6/14/2018	6/14/2019	2	Cooler	In hallway across from room 297	High Left	WF-06142018-012321	1/10/2019	FT-FY19-012019-012321-A	<1	FT-FY19-012019-012321-B	<1
WS-012322	6/14/2018	6/14/2019	2	Cooler	In hallway across from room 297	Low Right	WF-06142018-012322	1/10/2019	FT-FY19-012019-012322-A	<1	FT-FY19-012019-012322-B	<1
WS-012323	6/14/2018	6/14/2019	2	Break Room	In break room 298		WF-06142018-012323	1/10/2019	FT-FY19-012019-012323-A	<1	FT-FY19-012019-012323-B	<1
WS-012326	6/14/2018	6/14/2019	2	Cooler	In hallway adjacent to gym 260	High Left	WF-06142018-012326	1/10/2019	FT-FY19-012019-012326-A	<1	FT-FY19-012019-012326-B	<1
WS-012327	6/14/2018	6/14/2019	2	Cooler	In hallway adjacent to gym 260	Low Right	WF-06142018-012327	1/10/2019	FT-FY19-012019-012327-A	<1	FT-FY19-012019-012327-B	<1
WS-012328	6/14/2018	6/14/2019	2	Cooler	In gym 260	High Left	WF-06142018-012328	1/10/2019	FT-FY19-012019-012328-A	<1	FT-FY19-012019-012328-B	<1
WS-012329	6/14/2018	6/14/2019	2	Cooler	In gym 260	Low Right	WF-06142018-012329	1/10/2019	FT-FY19-012019-012329-A	<1	FT-FY19-012019-012329-B	<1
WS-012330	6/14/2018	6/14/2019	2	Break Room	In break room 251 (gym physical education office)		WF-06142018-012330	1/10/2019	FT-FY19-012019-012330-A	<1	FT-FY19-012019-012330-B	<1
WS-012332	6/14/2018	6/14/2019	2	Break Room	In break room 254		WF-06142018-012332	1/10/2019	FT-FY19-012019-012332-A	<1	FT-FY19-012019-012332-B	<1
WS-012334	6/14/2018	6/14/2019	2	Health Suite	In health suite in break room 228		WF-06142018-012334	1/10/2019	FT-FY19-012019-012334-A	<1	FT-FY19-012019-012334-B	<1
WS-012336	6/14/2018	6/14/2019	2	Health Suite	In health suite in dental suite 227	Left	WF-06142018-012336	1/10/2019	FT-FY19-012019-012336-A	<1	FT-FY19-012019-012336-B	<1
WS-012337	6/14/2018	6/14/2019	2	Health Suite	In health suite lab room 225E		WF-06142018-012337	1/10/2019	FT-FY19-012019-012337-A	<1	FT-FY19-012019-012337-B	<1
WS-012339	6/14/2018	6/14/2019	2	Health Suite	In health suite in dental suite 227 (handwash sink)	Right	WF-06142018-012339	1/10/2019	FT-FY19-012019-012339-A	<1	FT-FY19-012019-012339-B	<1
WS-012340	6/14/2018	6/14/2019	2	Health Suite	In health suite in exam room 225D		WF-06142018-012340	1/10/2019	FT-FY19-012019-012340-A	<1	FT-FY19-012019-012340-B	<1

WS- 012341	6/14/2018	6/14/2019	2	Health Suite	In health suite in exam room 225C	WF-06142018-012341	1/10/2019	FT-FY19-012019-012341-A	4.2	FT-FY19-012019-012341-B	<1
WS- 012342	6/14/2018	6/14/2019	2	Health Suite	In health suite in exam room 225A	WF-06142018-012342	1/10/2019	FT-FY19-012019-012342-A	<1	FT-FY19-012019-012342-B	<1

### Food Prep Sink

**Less than 5ppb - Devices requiring no remediation**

Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012265	1	Food Prep Sink	In kitchen first clockwise from entry door	1/10/2019	FT-FY19-012019-012265-A	<1	FT-FY19-012019-012265-B	<1