



# Eastern HS Lead in Water Test Results



## FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-002336	4/15/2019	4/15/2020	1	Combo Fountain	In classroom W143 Right	WF-04152019-002336	1/14/2020	FT-FY20-122019-002336-A	<1	FT-FY20-122019-002336-B	<1
WS-002339	4/15/2019	4/15/2020	1	Break Room	In break room W143 Right	WF-04152019-002339	1/14/2020	FT-FY20-122019-002339-A	1.5	FT-FY20-122019-002339-B	<1
WS-002342	4/15/2019	4/15/2020	1	Break Room	In break room W143 Left	WF-04152019-002342	1/14/2020	FT-FY20-122019-002342-A	1.9	FT-FY20-122019-002342-B	<1
WS-002345	4/15/2019	4/15/2020	1	Combo Fountain	In classroom W143 Left	WF-04152019-002345	1/14/2020	FT-FY20-122019-002345-A	<1	FT-FY20-122019-002345-B	<1
WS-008280	4/15/2019	4/15/2020	Basement	Ice Maker	In athletics training room G-12	WF-04152019-008280	1/14/2020	FT-FY20-122019-008280-A	<1	FT-FY20-122019-008280-B	<1
WS-010712	4/15/2019	4/15/2020	1	Health Suite	In health suite in exam room W128	WF-04152019-010712	1/14/2020	FT-FY20-122019-010712-A	<1	FT-FY20-122019-010712-B	<1
WS-010713	4/15/2019	4/15/2020	1	Health Suite	In health suite W131	WF-04152019-010713	1/14/2020	FT-FY20-122019-010713-A	<1	FT-FY20-122019-010713-B	<1
WS-010714	4/15/2019	4/15/2020	1	Health Suite	In health suite in exam room W134	WF-04152019-010714	1/14/2020	FT-FY20-122019-010714-A	<1	FT-FY20-122019-010714-B	<1
WS-010716	4/15/2019	4/15/2020	1	Cooler	In hallway across from room W130	WF-04152019-010716	1/14/2020	FT-FY20-122019-010716-A	<1	FT-FY20-122019-010716-B	<1
WS-010717	4/15/2019	4/15/2020	1	Bottle Filler	In hallway across from room W130 (bottle filler)	WF-04152019-010717	1/14/2020	FT-FY20-122019-010717-A	<1	FT-FY20-122019-010717-B	<1
WS-010722	4/15/2019	4/15/2020	Ground Floor	Cooler	In cafeteria Low Right	WF-04152019-010722	1/14/2020	FT-FY20-122019-010722-A	<1	FT-FY20-122019-010722-B	<1
WS-010723	4/15/2019	4/15/2020	Ground Floor	Cooler	In cafeteria High Left	WF-04152019-010723	1/14/2020	FT-FY20-122019-010723-A	<1	FT-FY20-122019-010723-B	<1
WS-010727	4/15/2019	4/15/2020	1	Break Room	In break room W110	WF-04152019-010727	1/14/2020	FT-FY20-122019-010727-A	<1	FT-FY20-122019-010727-B	<1
WS-010730	4/15/2019	4/15/2020	1	Cooler	In hallway adjacent to room E124	WF-04152019-010730	1/14/2020	FT-FY20-122019-010730-A	<1	FT-FY20-122019-010730-B	<1
WS-010766	4/15/2019	4/15/2020	1	Cooler	In hallway across from gym High Left	WF-04152019-010766	1/14/2020	FT-FY20-122019-010766-A	<1	FT-FY20-122019-010766-B	<1
WS-010767	4/15/2019	4/15/2020	1	Cooler	In hallway across from gym Low Right	WF-04152019-010767	1/14/2020	FT-FY20-122019-010767-A	<1	FT-FY20-122019-010767-B	<1
WS-010768	4/15/2019	4/15/2020	2	Cooler	In hallway across from room E218	WF-04152019-010768	1/14/2020	FT-FY20-122019-010768-A	<1	FT-FY20-122019-010768-B	<1
WS-010769	4/15/2019	4/15/2020	2	Bottle Filler	In hallway across from room E218 (bottle filler)	WF-04152019-010769	1/14/2020	FT-FY20-122019-010769-A	<1	FT-FY20-122019-010769-B	<1
WS-010775	4/15/2019	4/15/2020	2	Cooler	In hallway adjacent room E227	WF-04152019-010775	1/14/2020	FT-FY20-122019-010775-A	<1	FT-FY20-122019-010775-B	<1
WS-010783	4/15/2019	4/15/2020	2	Cooler	In hallway across from room W212 High Left	WF-04152019-010783	1/14/2020	FT-FY20-122019-010783-A	<1	FT-FY20-122019-010783-B	<1
WS-010784	4/15/2019	4/15/2020	2	Cooler	In hallway across from room W212 Low Right	WF-04152019-010784	1/14/2020	FT-FY20-122019-010784-A	<1	FT-FY20-122019-010784-B	<1
WS-010785	4/15/2019	4/15/2020	2	Break Room	In break room W209	WF-04152019-010785	1/14/2020	FT-FY20-122019-010785-A	<1	FT-FY20-122019-010785-B	<1
WS-010788	4/15/2019	4/15/2020	2	Break Room	In break room E211	WF-04152019-010788	1/14/2020	FT-FY20-122019-010788-A	<1	FT-FY20-122019-010788-B	<1
WS-010789	4/15/2019	4/15/2020	3	Cooler	In hallway across from room E316 Low Right	WF-04152019-010789	1/14/2020	FT-FY20-122019-010789-A	<1	FT-FY20-122019-010789-B	<1
WS-010790	4/15/2019	4/15/2020	3	Cooler	In hallway across from room E316 High Left	WF-04152019-010790	1/14/2020	FT-FY20-122019-010790-A	<1	FT-FY20-122019-010790-B	<1
WS-010816	4/15/2019	4/15/2020	4	Break Room	In breakroom (former science prep room) W406	WF-04152019-010816	1/14/2020	FT-FY20-122019-010816-A	<1	FT-FY20-122019-010816-B	<1
WS-010838	4/15/2019	4/15/2020	4	Cooler	In hallway across from room W411 Low Right	WF-04152019-010838	1/14/2020	FT-FY20-122019-010838-A	<1	FT-FY20-122019-010838-B	<1
WS-010839	4/15/2019	4/15/2020	4	Cooler	In hallway across from room W411 High Left	WF-04152019-010839	1/14/2020	FT-FY20-122019-010839-A	<1	FT-FY20-122019-010839-B	<1
WS-010965	4/15/2019	4/15/2020	Basement	Cooler	In boys locker room	WF-04152019-010965	1/14/2020	FT-FY20-122019-010965-A	<1	FT-FY20-122019-010965-B	<1
WS-010966	4/15/2019	4/15/2020	Basement	Cooler	In girls locker room	WF-04152019-010966	1/14/2020	FT-FY20-122019-010966-A	<1	FT-FY20-122019-010966-B	<1
WS-011887	4/15/2019	4/15/2020	4	Cooler	In hallway across from room E415 High Left	WF-04152019-011887	1/14/2020	FT-FY20-122019-011887-A	<1	FT-FY20-122019-011887-B	<1
WS-011888	4/15/2019	4/15/2020	4	Cooler	In hallway across from room E415 Low Right	WF-04152019-011888	1/14/2020	FT-FY20-122019-011888-A	<1	FT-FY20-122019-011888-B	<1

WS- 011890	10/14/2019	10/14/2020	3	Break Room	In breakroom E307	WF-10142019-011890	1/14/2020	FT-FY20-122019-011890-A	<1	FT-FY20-122019-011890-B	<1
WS- 011894	10/14/2019	10/14/2020	4	Break Room	In break room E406	WF-10142019-011894	1/14/2020	FT-FY20-122019-011894-A	<1	FT-FY20-122019-011894-B	<1

### Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010721	7/1/2019	7/1/2020	Ground Floor	Food Prep Sink	In kitchen first clockwise from entry door Left	WF-07012019-010721	1/14/2020	FT-FY20-122019-010721-A	<1	FT-FY20-122019-010721-B	<1

### FY20 Filter Test

Greater than 5ppb - Devices requiring remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010709	4/15/2019	4/15/2020	1	Health Suite	In health suite W130	WF-04152019-010709	1/14/2020	FT-FY20-122019-010709-A	6.4	FT-FY20-122019-010709-B	<1
WS- 010711	4/15/2019	4/15/2020	1	Health Suite	In health suite in lab room W129	WF-04152019-010711	1/14/2020	FT-FY20-122019-010711-A	6.8	FT-FY20-122019-010711-B	1