



# Eastern High School Lead in Water Test Results

## FY24 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008280	3/13/2023	3/13/2024	Basement	Ice Maker	In athletics training room G-12	WF-03132023-008280	1/4/2024	FT-FY24-11012023-008280-A	<1	FT-FY24-11012023-008280-B	<1
WS- 010709	3/13/2023	3/13/2024	1	Health Suite	In health suite W130	WF-03132023-010709	1/4/2024	FT-FY24-11012023-010709-A	2.3	FT-FY24-11012023-010709-B	3.9
WS- 010711	3/13/2023	3/13/2024	1	Health Suite	In health suite in lab room W129	WF-03132023-010711	1/4/2024	FT-FY24-11012023-010711-A	<1	FT-FY24-11012023-010711-B	<1
WS- 010712	3/13/2023	3/13/2024	1	Health Suite	In health suite in exam room W128	WF-03132023-010712	1/4/2024	FT-FY24-11012023-010712-A	1.1	FT-FY24-11012023-010712-B	4.5
WS- 010713	3/13/2023	3/13/2024	1	Health Suite	In health suite W131	WF-03132023-010713	1/4/2024	FT-FY24-11012023-010713-A	<1	FT-FY24-11012023-010713-B	1.1
WS- 010714	3/13/2023	3/13/2024	1	Health Suite	In health suite in exam room W134	WF-03132023-010714	1/4/2024	FT-FY24-11012023-010714-A	<1	FT-FY24-11012023-010714-B	<1
WS- 010716	3/13/2023	3/13/2024	1	Cooler	In hallway across from room W130	WF-03132023-010716	1/4/2024	FT-FY24-11012023-010716-A	<1	FT-FY24-11012023-010716-B	<1
WS- 010717	3/13/2023	3/13/2024	1	Bottle Filler	In hallway across from room W130 (bottle filler)	WF-03132023-010717	1/4/2024	FT-FY24-11012023-010717-A	<1	FT-FY24-11012023-010717-B	<1
WS- 010722	3/13/2023	3/13/2024	Ground Floor	Cooler	In cafeteria Low Right	WF-03132023-010722	1/4/2024	FT-FY24-11012023-010722-A	<1	FT-FY24-11012023-010722-B	<1
WS- 010723	3/13/2023	3/13/2024	Ground Floor	Cooler	In cafeteria High Left	WF-03132023-010723	1/4/2024	FT-FY24-11012023-010723-A	<1	FT-FY24-11012023-010723-B	<1
WS- 010727	3/13/2023	3/13/2024	1	Break Room	In break room W110	WF-03132023-010727	1/4/2024	FT-FY24-11012023-010727-A	<1	FT-FY24-11012023-010727-B	<1
WS- 010766	3/13/2023	3/13/2024	1	Cooler	In hallway across from gym High Left	WF-03132023-010766	1/4/2024	FT-FY24-11012023-010766-A	<1	FT-FY24-11012023-010766-B	<1
WS- 010767	3/13/2023	3/13/2024	1	Cooler	In hallway across from gym Low Right	WF-03132023-010767	1/4/2024	FT-FY24-11012023-010767-A	<1	FT-FY24-11012023-010767-B	<1
WS- 010768	3/13/2023	3/13/2024	2	Cooler	In hallway across from room E218	WF-03132023-010768	1/4/2024	FT-FY24-11012023-010768-A	<1	FT-FY24-11012023-010768-B	<1
WS- 010769	3/13/2023	3/13/2024	2	Bottle Filler	In hallway across from room E218 (bottle filler)	WF-03132023-010769	1/4/2024	FT-FY24-11012023-010769-A	<1	FT-FY24-11012023-010769-B	<1
WS- 010775	3/13/2023	3/13/2024	2	Cooler	In hallway adjacent room E227	WF-03132023-010775	1/4/2024	FT-FY24-11012023-010775-A	<1	FT-FY24-11012023-010775-B	<1
WS- 010783	3/13/2023	3/13/2024	2	Cooler	In hallway across from room W212 High Left	WF-03132023-010783	1/4/2024	FT-FY24-11012023-010783-A	<1	FT-FY24-11012023-010783-B	<1
WS- 010784	3/13/2023	3/13/2024	2	Cooler	In hallway across from room W212 Low Right	WF-03132023-010784	1/4/2024	FT-FY24-11012023-010784-A	<1	FT-FY24-11012023-010784-B	<1
WS- 010785	3/13/2023	3/13/2024	2	Break Room	In break room W209	WF-03132023-010785	1/4/2024	FT-FY24-11012023-010785-A	<1	FT-FY24-11012023-010785-B	<1
WS- 010788	3/13/2023	3/13/2024	2	Break Room	In break room E211	WF-03132023-010788	1/4/2024	FT-FY24-11012023-010788-A	<1	FT-FY24-11012023-010788-B	<1
WS- 010789	3/13/2023	3/13/2024	3	Cooler	In hallway across from room E316 Low Right	WF-03132023-010789	1/4/2024	FT-FY24-11012023-010789-A	<1	FT-FY24-11012023-010789-B	<1
WS- 010790	3/13/2023	3/13/2024	3	Cooler	In hallway across from room E316 High Left	WF-03132023-010790	1/4/2024	FT-FY24-11012023-010790-A	<1	FT-FY24-11012023-010790-B	<1
WS- 010838	3/13/2023	3/13/2024	4	Cooler	In hallway across from room W411 Low Right	WF-03132023-010838	1/4/2024	FT-FY24-11012023-010838-A	<1	FT-FY24-11012023-010838-B	<1
WS- 010839	3/13/2023	3/13/2024	4	Cooler	In hallway across from room W411 High Left	WF-03132023-010839	1/4/2024	FT-FY24-11012023-010839-A	<1	FT-FY24-11012023-010839-B	<1
WS- 010965	3/13/2023	3/13/2024	Basement	Cooler	In boys locker room	WF-03132023-010965	1/4/2024	FT-FY24-11012023-010965-A	<1	FT-FY24-11012023-010965-B	<1
WS- 011887	3/13/2023	3/13/2024	4	Cooler	In hallway across from room E415 High Left	WF-03132023-011887	1/4/2024	FT-FY24-11012023-011887-A	<1	FT-FY24-11012023-011887-B	<1
WS- 011888	3/13/2023	3/13/2024	4	Cooler	In hallway across from room E415 Low Right	WF-03132023-011888	1/4/2024	FT-FY24-11012023-011888-A	<1	FT-FY24-11012023-011888-B	<1
WS- 011890	9/6/2023	9/6/2024	3	Break Room	In breakroom E307	WF-09062023-011890	1/4/2024	FT-FY24-11012023-011890-A	3.0	FT-FY24-11012023-011890-B	<1
WS- 011894	9/6/2023	9/6/2024	4	Break Room	In break room E406	WF-09062023-011894	1/4/2024	FT-FY24-11012023-011894-A	1.3	FT-FY24-11012023-011894-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010721	1/18/2023	1/18/2024	Ground Floor	Food Prep Sink	In kitchen first clockwise from entry door Left	WF-01182023-010721	1/4/2024	FT-FY24-11012023-010721-A	<1	FT-FY24-11012023-010721-B	<1