



Eastern HS Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 002336	4/23/2018	4/23/2019	1	Combo Fountain	In classroom W143	Right	WF-04232018-002336	1/10/2019	FT-FY19-012019-002336-A	<1	FT-FY19-012019-002336-B	<1
WS- 002339	4/23/2018	4/23/2019	1	Break Room	In break room W143	Right	WF-04232018-002339	1/10/2019	FT-FY19-012019-002339-A	1.8	FT-FY19-012019-002339-B	<1
WS- 002342	4/23/2018	4/23/2019	1	Break Room	In break room W143	Left	WF-04232018-002342	1/10/2019	FT-FY19-012019-002342-A	<1	FT-FY19-012019-002342-B	<1
WS- 002345	4/23/2018	4/23/2019	1	Combo Fountain	In classroom W143	Left	WF-04232018-002345	1/10/2019	FT-FY19-012019-002345-A	<1	FT-FY19-012019-002345-B	<1
WS- 008280	4/23/2018	4/23/2019	Basement	Ice Maker	In athletics training room G-12		WF-04232018-008280	1/10/2019	FT-FY19-012019-008280-A	<1	FT-FY19-012019-008280-B	<1
WS- 010709	4/23/2018	4/23/2019	1	Health Suite	In health suite W130		WF-04232018-010709	1/10/2019	FT-FY19-012019-010709-A	<1	FT-FY19-012019-010709-B	<1
WS- 010711	4/23/2018	4/23/2019	1	Health Suite	In health suite in lab room W129		WF-04232018-010711	1/10/2019	FT-FY19-012019-010711-A	<1	FT-FY19-012019-010711-B	<1
WS- 010712	4/23/2018	4/23/2019	1	Health Suite	In health suite in exam room W128		WF-04232018-010712	1/10/2019	FT-FY19-012019-010712-A	<1	FT-FY19-012019-010712-B	<1
WS- 010713	4/23/2018	4/23/2019	1	Health Suite	In health suite W131		WF-04232018-010713	1/10/2019	FT-FY19-012019-010713-A	<1	FT-FY19-012019-010713-B	<1
WS- 010714	4/23/2018	4/23/2019	1	Health Suite	In health suite in exam room W134		WF-04232018-010714	1/10/2019	FT-FY19-012019-010714-A	<1	FT-FY19-012019-010714-B	<1
WS- 010716	8/3/2018	8/3/2019	1	Cooler	In hallway across from room W130		WF-08032018-010716	1/10/2019	FT-FY19-012019-010716-A	<1	FT-FY19-012019-010716-B	<1
WS- 010717	8/3/2018	8/3/2019	1	Bottle Filler	In hallway across from room W130 (bottle filler)		WF-08032018-010717	1/10/2019	FT-FY19-012019-010717-A	<1	FT-FY19-012019-010717-B	<1
WS- 010722	4/23/2018	4/23/2019	Ground Floor	Cooler	In cafeteria	Low Right	WF-04232018-010722	1/10/2019	FT-FY19-012019-010722-A	<1	FT-FY19-012019-010722-B	<1
WS- 010723	4/23/2018	4/23/2019	Ground Floor	Cooler	In cafeteria	High Left	WF-04232018-010723	1/10/2019	FT-FY19-012019-010723-A	<1	FT-FY19-012019-010723-B	<1
WS- 010727	4/23/2018	4/23/2019	1	Break Room	In break room W110		WF-04232018-010727	1/10/2019	FT-FY19-012019-010727-A	<1	FT-FY19-012019-010727-B	<1
WS- 010730	4/23/2018	4/23/2019	1	Cooler	In hallway adjacent to room E124		WF-04232018-010730	1/10/2019	FT-FY19-012019-010730-A	<1	FT-FY19-012019-010730-B	<1
WS- 010766	4/23/2018	4/23/2019	1	Cooler	In hallway across from gym	High Left	WF-04232018-010766	1/10/2019	FT-FY19-012019-010766-A	<1	FT-FY19-012019-010766-B	<1
WS- 010767	4/23/2018	4/23/2019	1	Cooler	In hallway across from gym	Low Right	WF-04232018-010767	1/10/2019	FT-FY19-012019-010767-A	<1	FT-FY19-012019-010767-B	<1
WS- 010768	8/3/2018	8/3/2019	2	Cooler	In hallway across from room E218		WF-08032018-010768	1/10/2019	FT-FY19-012019-010768-A	<1	FT-FY19-012019-010768-B	<1
WS- 010769	8/3/2018	8/3/2019	2	Bottle Filler	In hallway across from room E218 (bottle filler)		WF-08032018-010769	1/10/2019	FT-FY19-012019-010769-A	<1	FT-FY19-012019-010769-B	<1
WS- 010775	4/23/2018	4/23/2019	2	Cooler	In hallway adjacent room E227		WF-04232018-010775	1/10/2019	FT-FY19-012019-010775-A	<1	FT-FY19-012019-010775-B	<1
WS- 010783	4/23/2018	4/23/2019	2	Cooler	In hallway across from room W212	High Left	WF-04232018-010783	1/10/2019	FT-FY19-012019-010783-A	<1	FT-FY19-012019-010783-B	<1
WS- 010784	4/23/2018	4/23/2019	2	Cooler	In hallway across from room W212	Low Right	WF-04232018-010784	1/10/2019	FT-FY19-012019-010784-A	<1	FT-FY19-012019-010784-B	<1
WS- 010785	4/23/2018	4/23/2019	2	Break Room	In break room W209		WF-04232018-010785	1/10/2019	FT-FY19-012019-010785-A	<1	FT-FY19-012019-010785-B	<1
WS- 010788	4/23/2018	4/23/2019	2	Break Room	In break room E211		WF-04232018-010788	1/10/2019	FT-FY19-012019-010788-A	<1	FT-FY19-012019-010788-B	<1
WS- 010789	4/23/2018	4/23/2019	3	Cooler	In hallway across from room E316	Low Right	WF-04232018-010789	1/10/2019	FT-FY19-012019-010789-A	<1	FT-FY19-012019-010789-B	<1
WS- 010790	4/23/2018	4/23/2019	3	Cooler	In hallway across from room E316	High Left	WF-04232018-010790	1/10/2019	FT-FY19-012019-010790-A	<1	FT-FY19-012019-010790-B	<1
WS- 010793	4/23/2018	4/23/2019	3	Cooler	In hallway across from room W311	High Left	WF-04232018-010793	1/10/2019	FT-FY19-012019-010793-A	<1	FT-FY19-012019-010793-B	<1
WS- 010794	4/23/2018	4/23/2019	3	Cooler	In hallway across from room W311	Low Right	WF-04232018-010794	1/10/2019	FT-FY19-012019-010794-A	<1	FT-FY19-012019-010794-B	<1
WS- 010816	4/23/2018	4/23/2019	4	Break Room	In breakroom (former science prep room) W406		WF-04232018-010816	1/10/2019	FT-FY19-012019-010816-A	<1	FT-FY19-012019-010816-B	<1
WS- 010838	4/23/2018	4/23/2019	4	Cooler	In hallway across from room W411	Low Right	WF-04232018-010838	1/10/2019	FT-FY19-012019-010838-A	<1	FT-FY19-012019-010838-B	<1
WS- 010839	4/23/2018	4/23/2019	4	Cooler	In hallway across from room W411	High Left	WF-04232018-010839	1/10/2019	FT-FY19-012019-010839-A	<1	FT-FY19-012019-010839-B	<1
WS- 010965	12/28/2018	12/28/2019	Basement	Cooler	In boys locker room		WF-12282018-010965	1/10/2019	FT-FY19-012019-010965-A	<1	FT-FY19-012019-010965-B	<1
WS- 011887	4/23/2018	4/23/2019	4	Cooler	In hallway across from room E415	High Left	WF-04232018-011887	1/10/2019	FT-FY19-012019-011887-A	<1	FT-FY19-012019-011887-B	<1
WS- 011888	4/23/2018	4/23/2019	4	Cooler	In hallway across from room E415	Low Right	WF-04232018-011888	1/10/2019	FT-FY19-012019-011888-A	<1	FT-FY19-012019-011888-B	<1

WS- 011890	10/24/2018	10/24/2019	3	Break Room	In breakroom E307	WF-10242018-011890	1/10/2019	FT-FY19-012019-011890-A	<1	FT-FY19-012019-011890-B	<1
WS- 011894	10/24/2018	10/24/2019	4	Break Room	In break room E406	WF-10242018-011894	1/10/2019	FT-FY19-012019-011894-A	<1	FT-FY19-012019-011894-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation										
Record ID	Floor	Device Type	Device Location			Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010718	Ground Floor	Food Prep Sink	In kitchen fourth clockwise from entry door			1/10/2019	FT-FY19-012019-010718-A	<1	FT-FY19-012019-010718-B	<1
WS- 010720	Ground Floor	Food Prep Sink	In kitchen second clockwise from entry door		Right	1/10/2019	FT-FY19-012019-010720-A	<1	FT-FY19-012019-010720-B	<1
WS- 010721	Ground Floor	Food Prep Sink	In kitchen first clockwise from entry door		Left	1/10/2019	FT-FY19-012019-010721-A	<1	FT-FY19-012019-010721-B	<1