



# Emery RC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005485	5/3/2018	5/3/2019	2	Cooler	In hallway across from elevator	High Left	WF-05032018-005485	2/14/2019	FT-FY19-022019-005485-A	<1	FT-FY19-022019-005485-B	<1
WS- 005486	5/3/2018	5/3/2019	2	Cooler	In hallway across from elevator	Low Right	WF-05032018-005486	2/14/2019	FT-FY19-022019-005486-A	<1	FT-FY19-022019-005486-B	<1
WS- 005491	5/3/2018	5/3/2019	1	Cooler	In hallway adjacent to gym 115	High Left	WF-05032018-005491	2/14/2019	FT-FY19-022019-005491-A	<1	FT-FY19-022019-005491-B	<1
WS- 005492	5/3/2018	5/3/2019	1	Cooler	In hallway adjacent to gym 116	Low Right	WF-05032018-005492	2/14/2019	FT-FY19-022019-005492-A	<1	FT-FY19-022019-005492-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005480	5/3/2018	5/3/2019	1	Food Prep Sink	In pantry room 114		WF-05032018-005480	2/14/2019	FT-FY19-022019-005480-A	<1	FT-FY19-022019-005480-B	<1