



J.O. Wilson ES Lead Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001904	5/10/2017	5/10/2018	1	Cooler	In hallway adjacent to main lobby	WF-52017-001904	10/24/2017	FT-FY18-102017-001904-A	< 1	FT-FY18-102017-001904-B	< 1
WS- 001912	10/9/2017	10/9/2018	1	Combo Faucet	In classroom 111 Right	WF-102017-001912	10/24/2017	FT-FY18-102017-001912-A	< 1	FT-FY18-102017-001912-B	< 1
WS- 001913	5/10/2017	5/10/2018	1	Combo Fountain	In classroom 110 Left	WF-52017-001913	10/24/2017	FT-FY18-102017-001913-A	2.1	FT-FY18-102017-001913-B	< 1
WS- 001915	5/10/2017	5/10/2018	1	Cooler	In hallway adjacent to south stairwell	WF-52017-001915	10/24/2017	FT-FY18-102017-001915-A	< 1	FT-FY18-102017-001915-B	< 1
WS- 001917	5/10/2017	5/10/2018	2	Cooler	In hallway adjacent to north stairwell	WF-52017-001917	10/24/2017	FT-FY18-102017-001917-A	< 1	FT-FY18-102017-001917-B	< 1
WS- 001918	5/10/2017	5/10/2018	1	Cooler	In hallway adjacent to room 121	WF-52017-001918	10/24/2017	FT-FY18-102017-001918-A	< 1	FT-FY18-102017-001918-B	< 1
WS- 001919	10/9/2017	10/9/2018	1	Classroom Faucet	In classroom 121 in left wing Left	WF-102017-001919	10/24/2017	FT-FY18-102017-001919-A	< 1	FT-FY18-102017-001919-B	< 1
WS- 001926	5/10/2017	5/10/2018	2	Cooler	In hallway adjacent to server room	WF-52017-001926	10/24/2017	FT-FY18-102017-001926-A	< 1	FT-FY18-102017-001926-B	< 1
WS- 001930	5/10/2017	5/10/2018	2	Combo Fountain	In classroom 222	WF-52017-001930	10/24/2017	FT-FY18-102017-001930-A	< 1	FT-FY18-102017-001930-B	< 1
WS- 001933	10/9/2017	10/9/2018	2	Classroom Faucet	In classroom 221	WF-102017-001933	10/24/2017	FT-FY18-102017-001933-A	< 1	FT-FY18-102017-001933-B	< 1
WS- 001934	5/10/2017	5/10/2018	2	Combo Fountain	In classroom 221 Left	WF-52017-001934	10/24/2017	FT-FY18-102017-001934-A	1.3	FT-FY18-102017-001934-B	< 1
WS- 001935	10/9/2017	10/9/2018	2	Combo Faucet	In classroom 221 Right	WF-102017-001935	10/24/2017	FT-FY18-102017-001935-A	< 1	FT-FY18-102017-001935-B	< 1
WS- 001941	5/10/2017	5/10/2018	3	Cooler	In hallway adjacent to south stairwell	WF-52017-001941	10/24/2017	FT-FY18-102017-001941-A	< 1	FT-FY18-102017-001941-B	< 1
WS- 001943	5/10/2017	5/10/2018	3	Cooler	In hallway adjacent to north stairwell	WF-52017-001943	10/24/2017	FT-FY18-102017-001943-A	< 1	FT-FY18-102017-001943-B	< 1
WS- 001944	5/10/2017	5/10/2018	3	Cooler	In hallway adjacent to room 329	WF-52017-001944	10/24/2017	FT-FY18-102017-001944-A	< 1	FT-FY18-102017-001944-B	< 1
WS- 001948	5/10/2017	5/10/2018	3	Cooler	In classroom 322	WF-52017-001948	10/24/2017	FT-FY18-102017-001948-A	< 1	FT-FY18-102017-001948-B	< 1

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001900	1	Food Prep Sink	In kitchen first clockwise from entry door Left	10/24/2017	FT-FY18-102017-001900-A	< 1	FT-FY18-102017-001900-B	< 1
WS- 001901	1	Food Prep Sink	In kitchen second clockwise from entry door Right	10/24/2017	FT-FY18-102017-001901-A	< 1	FT-FY18-102017-001901-B	< 1