



School Within School @ Goding Lead Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation											
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010560	6/27/2017	6/27/2018	Ground Floor	Health Suite	In health suite	WF-62017-010560	10/25/2017	FT-FY18-102017-010560-A	< 1	FT-FY18-102017-010560-B	< 1
WS- 010561	10/11/2017	10/11/2018	Ground Floor	Classroom Faucet	In classroom 007	WF-102017-010561	10/25/2017	FT-FY18-102017-010561-A	< 1	FT-FY18-102017-010561-B	< 1
WS- 010572	6/27/2017	6/27/2018	2	Cooler	In hallway adjacent to room 203	WF-62017-010572	10/25/2017	FT-FY18-102017-010572-A	< 1	FT-FY18-102017-010572-B	< 1
WS- 010587	6/27/2017	6/27/2018	3	Cooler	In hallway adjacent to room 303	WF-62017-010587	10/25/2017	FT-FY18-102017-010587-A	< 1	FT-FY18-102017-010587-B	< 1
WS- 010589	6/27/2017	6/27/2018	4	Cooler	In hallway adjacent to staff restroom	WF-62017-010589	10/25/2017	FT-FY18-102017-010589-A	< 1	FT-FY18-102017-010589-B	< 1
WS- 010590	6/27/2017	6/27/2018	4	Cooler	In hallway adjacent to room 403	WF-62017-010590	10/25/2017	FT-FY18-102017-010590-A	< 1	FT-FY18-102017-010590-B	< 1

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation										
RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)		
WS- 010565	Ground Floor	Food Prep Sink	In kitchen Right	10/25/2017	FT-FY18-102017-010565-A	2.4	FT-FY18-102017-010565-B	< 1		