



Watkins ES Lead Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009392	8/16/2017	8/16/2018	1	Combo Fountain	In classroom 110	WF-82017-009392	10/25/2017	FT-FY18-102017-009392-A	< 1	FT-FY18-102017-009392-B	< 1
WS- 009394	8/16/2017	8/16/2018	1	Combo Fountain	In classroom 115	WF-82017-009394	10/25/2017	FT-FY18-102017-009394-A	< 1	FT-FY18-102017-009394-B	< 1
WS- 009475	8/16/2017	8/16/2018	1	Combo Fountain	In classroom 125	WF-82017-009475	10/25/2017	FT-FY18-102017-009475-A	< 1	FT-FY18-102017-009475-B	< 1
WS- 009479	8/16/2017	8/16/2018	1	Combo Fountain	In classroom 140	WF-82017-009479	10/25/2017	FT-FY18-102017-009479-A	< 1	FT-FY18-102017-009479-B	< 1
WS- 009482	8/16/2017	8/16/2018	1	Cooler	In gym room 190	WF-82017-009482	10/25/2017	FT-FY18-102017-009482-A	< 1	FT-FY18-102017-009482-B	< 1
WS- 009503	8/16/2017	8/16/2018	1	Cooler	In hallway across from gym room 190	WF-82017-009503	10/25/2017	FT-FY18-102017-009503-A	< 1	FT-FY18-102017-009503-B	< 1
WS- 009506	8/16/2017	8/16/2018	1	Health Suite	In health suite room 121	WF-82017-009506	10/25/2017	FT-FY18-102017-009506-A	< 1	FT-FY18-102017-009506-B	< 1
WS- 009507	8/16/2017	8/16/2018	1	Break Room	In staff workroom 104	WF-82017-009507	10/25/2017	FT-FY18-102017-009507-A	< 1	FT-FY18-102017-009507-B	< 1
WS- 010110	8/16/2017	8/16/2018	4	Combo Fountain	In classroom 435	WF-82017-010110	10/25/2017	FT-FY18-102017-010110-A	< 1	FT-FY18-102017-010110-B	< 1
WS- 010111	8/16/2017	8/16/2018	4	Bottle Filler	In hallway across from elevator 4th floor	WF-82017-010111	10/25/2017	FT-FY18-102017-010111-A	< 1	FT-FY18-102017-010111-B	< 1
WS- 010112	8/16/2017	8/16/2018	4	Cooler	In hallway across from elevator 4th floor	WF-82017-010112	10/25/2017	FT-FY18-102017-010112-A	< 1	FT-FY18-102017-010112-B	< 1
WS- 010119	8/16/2017	8/16/2018	3	Break Room	In staff lounge 311B	WF-82017-010119	10/25/2017	FT-FY18-102017-010119-A	< 1	FT-FY18-102017-010119-B	< 1
WS- 010123	8/16/2017	8/16/2018	2	Break Room	In staff workroom 204	WF-82017-010123	10/25/2017	FT-FY18-102017-010123-A	< 1	FT-FY18-102017-010123-B	< 1
WS- 010220	8/16/2017	8/16/2018	2	Combo Fountain	In classroom 210	WF-82017-010220	10/25/2017	FT-FY18-102017-010220-A	< 1	FT-FY18-102017-010220-B	< 1
WS- 010225	8/16/2017	8/16/2018	2	Bottle Filler	In hallway across from elevator 2nd floor	WF-82017-010225	10/25/2017	FT-FY18-102017-010225-A	< 1	FT-FY18-102017-010225-B	< 1

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009485	1	Food Prep Sink	In kitchen 1st clockwise from entry door	10/25/2017	FT-FY18-102017-009485-A	< 1	FT-FY18-102017-009485-B	< 1