



# FEREBEE REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 FEREBEE-HOPE RECREATION	5/24/2016	WS- 005690	Cooler	1	In main hallway adjacent to gymnasium Right	WT-042916-5707- A	< 1	WT-042916-5707- B	< 1				
2 FEREBEE-HOPE RECREATION	5/24/2016	WS- 005691	Cooler	1	In hallway adjacent to girl's gymnasium Left	WT-042916-5708- A	< 1	WT-042916-5708- B	< 1				
3 FEREBEE-HOPE RECREATION	5/24/2016	WS- 005695	Cooler	1	In women's locker room	WT-042916-5712- A	< 1	WT-042916-5712- B	< 1				
4 FEREBEE-HOPE RECREATION	5/24/2016	WS- 005696	Fountain	Ground Floor	Exterior facing main entrance Low	WT-042916-5713- A	< 1	WT-042916-5713- B	< 1				
5 FEREBEE-HOPE RECREATION	5/24/2016	WS- 005697	Fountain	Ground Floor	In playground facing main entrance Low	WT-042916-5714- A	< 1	WT-042916-5714- B	< 1				
6 FEREBEE-HOPE RECREATION	5/24/2016	WS- 005698	Fountain	Ground Floor	Exterior facing main door entrance High	WT-042916-5715- A	< 1	WT-042916-5715- B	< 1				
7 FEREBEE-HOPE RECREATION	5/24/2016	WS- 005699	Fountain	Ground Floor	Exterior in playground facing main door entrance High	WT-042916-5716- A	< 1	WT-042916-5716- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.