



# Filmore Arts Center Lead in Water Test Results

## FY23 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008762	4/27/2022	4/27/2023	3	Break Room	In staff lounge 339	WF-04272022-008762	1/18/2023	FT-FY23-01092023-008762-A	<1	FT-FY23-01092023-008762-B	<1