



Filmore Arts Center Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008762	4/22/2019	4/22/2020	3	Break Room	In staff lounge 339	WF-04222019-008762	1/6/2020	FT-FY20-122019-008762-A	<1	FT-FY20-122019-008762-B	<1
WS- 008763	4/22/2019	4/22/2020	3	Cooler	In hallway across from classroom 302 High Left	WF-04222019-008763	1/6/2020	FT-FY20-122019-008763-A	<1	FT-FY20-122019-008763-B	<1
WS- 008764	4/22/2019	4/22/2020	3	Cooler	In hallway across from classroom 302 Low Right	WF-04222019-008764	1/6/2020	FT-FY20-122019-008764-A	<1	FT-FY20-122019-008764-B	<1