



Filmore Arts Center Lead in Water Test Results

FY22 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008762	5/10/2021	5/10/2022	3	Break Room	In staff lounge 339	WF-05102021-008762	1/23/2022	FT-FY22-01042022-008762-A	<1	FT-FY22-01042022-008762-B	<1