



Filmore Arts Center Lead in Water Test Results

FY21 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008762	6/10/2020	6/10/2021	3	Break Room	In staff lounge 339	WF-06102020-008762	4/7/2021	FT-FY21-032021-008762-A	<1	FT-FY21-032021-008762-B	<1