



FORT GREBLE PARK LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 FORT GREBLE PARK	5/20/2016	WS- 003781	Utility	Ground Floor	In utility room (water source)	WT-042916-3798- A	26.6	WT-042916-3798- B	60.8	Not accessible to children			
2 FORT GREBLE PARK	5/20/2016	WS- 003782	Fountain	Ground Floor	In main house adjacent to bathroom	WT-042916-3799- A	77.8	WT-042916-3799- B	162	Filtered	7/1/2016	<1	<1
3 FORT GREBLE PARK	5/20/2016	WS- 010066	Fountain	Ground Floor	In exterior adjacent to basketball court	High	WT-042916-10083- A	< 2	WT-042916-10083- B	< 2			
4 FORT GREBLE PARK	5/20/2016	WS- 010067	Fountain	Ground Floor	Adjacent to Basketball court	Low	WT-042916-10084- A	< 2	WT-042916-10084- B	< 2			
5 FORT GREBLE PARK	5/20/2016	WS- 010068	Fountain	Ground Floor	In exterior adjacent to water slide	Left Low	WT-042916-10085- A	< 2	WT-042916-10085- B	< 2			
6 FORT GREBLE PARK	5/20/2016	WS- 010069	Fountain	Ground Floor	In exterior adjacent to water slide	Right High	WT-042916-10086- A	< 2	WT-042916-10086- B	< 2			

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.