



Fort Stanton RC Lead Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

| RECORD ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | WATER FILTERS Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) | |
|------------|-----------------------|------------------------|-----------------|-------------|------------------------------------|--------------------|-----------------|----------------------|----------------------------------|----------------------|----------------------------------|----|
| WS- 006231 | 6/29/17 | 6/29/18 | Ground Floor | Cooler | In lobby adjacent to elevator | Left High | WF-62017-006231 | 3/7/18 | FT-FY18--62017-006231-A | <1 | FT-FY18--62017-006231-B | <1 |
| WS- 006234 | 6/29/17 | 6/29/18 | Ground Floor | Cooler | In hallway adjacent to kitchen 103 | Right Low | WF-62017-006234 | 3/7/18 | FT-FY18--62017-006234-A | <1 | FT-FY18--62017-006234-B | <1 |

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

| RECORD ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | WATER FILTERS Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
|------------|-----------------------|------------------------|-----------------|----------------|-----------------|--------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| WS- 006235 | 6/29/17 | 6/29/18 | Ground Floor | Food Prep Sink | In kitchen 103 | WF-62017-006235 | 3/7/18 | FT-FY18--62017-006235-A | <1 | FT-FY18--62017-006235-B | <1 |