



# Fort Stanton RC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 006231	5/9/2018	5/9/2019	Ground Floor	Cooler	In lobby adjacent to elevator	High Left	WF-05092018-006231	3/19/2019	FT-FY19-032019-006231-A	<1	FT-FY19-032019-006231-B	<1	
WS- 006232	5/9/2018	5/9/2019	Ground Floor	Cooler	In lobby adjacent to elevator	Low Right	WF-05092018-006232	3/19/2019	FT-FY19-032019-006232-A	<1	FT-FY19-032019-006232-B	<1	
WS- 006233	5/9/2018	5/9/2019	Ground Floor	Cooler	In hallway adjacent to kitchen 103	High Left	WF-05092018-006233	3/19/2019	FT-FY19-032019-006233-A	<1	FT-FY19-032019-006233-B	<1	
WS- 006234	5/9/2018	5/9/2019	Ground Floor	Cooler	In hallway adjacent to kitchen 103	Low Right	WF-05092018-006234	3/19/2019	FT-FY19-032019-006234-A	<1	FT-FY19-032019-006234-B	<1	

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 006235	5/9/2018	5/9/2019	Ground Floor	Food Prep Sink	In kitchen 103		WF-05092018-006235	3/19/2019	FT-FY19-032019-006235-A	<1	FT-FY19-032019-006235-B	<1	