



Fort Stanton RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006231	4/19/2019	4/19/2020	Ground Floor	Cooler	In lobby adjacent to elevator	High	Left	WF-04192019-006231	3/18/2020	FT-FY20-012020-006231-A	<1	FT-FY20-012020-006231-B	<1
WS- 006232	4/19/2019	4/19/2020	Ground Floor	Cooler	In lobby adjacent to elevator	Low	Right	WF-04192019-006232	3/18/2020	FT-FY20-012020-006232-A	<1	FT-FY20-012020-006232-B	<1
WS- 006233	4/19/2019	4/19/2020	Ground Floor	Cooler	In hallway adjacent to kitchen 103	High	Left	WF-04192019-006233	3/18/2020	FT-FY20-012020-006233-A	<1	FT-FY20-012020-006233-B	<1
WS- 006234	4/19/2019	4/19/2020	Ground Floor	Cooler	In hallway adjacent to kitchen 103	Low	Right	WF-04192019-006234	3/18/2020	FT-FY20-012020-006234-A	<1	FT-FY20-012020-006234-B	<1
WS- 006235	4/19/2019	4/19/2020	Ground Floor	Food Prep Sink	In kitchen 103			WF-04192019-006235	3/18/2020	FT-FY20-012020-006235-A	<1	FT-FY20-012020-006235-B	<1