



Fort Stevens RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-012703	5/17/2018	5/17/2019	Ground Floor	Cooler	In Rec center adjacent to women's bathroom Low Left	WF-05172018-012703	2/14/2019	FT-FY19-022019-012703-A	<1	FT-FY19-022019-012703-B	<1
WS-012704	5/17/2018	5/17/2019	Ground Floor	Cooler	In Rec center adjacent to women's bathroom Right	WF-05172018-012704	2/14/2019	FT-FY19-022019-012704-A	<1	FT-FY19-022019-012704-B	<1
WS-012705	7/11/2018	7/11/2019	Ground Floor	Bottle Filler	In Senior Center adjacent to kitchen (bottle filler)	WF-07112018-012705	2/14/2019	FT-FY19-022019-012705-A	<1	FT-FY19-022019-012705-B	<1
WS-012706	7/11/2018	7/11/2019	Ground Floor	Cooler	In Senior Center adjacent to kitchen High Left	WF-07112018-012706	2/14/2019	FT-FY19-022019-012706-A	<1	FT-FY19-022019-012706-B	<1
WS-012707	5/17/2018	5/17/2019	Ground Floor	Cooler	In Senior Center adjacent to kitchen Low Right	WF-05172018-012707	2/14/2019	FT-FY19-022019-012707-A	<1	FT-FY19-022019-012707-B	<1