



Garfield ES Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004519	4/13/2018	4/13/2019	Basement	Cooler	In cafeteria adjacent to entry door	WF-04132018-004519	10/23/2018	FT-FY19-102018-004519-A	< 1	FT-FY19-102018-004519-B	< 1
WS- 004520	4/13/2018	4/13/2019	Basement	Cooler	In cafeteria adjacent to kitchen	WF-04132018-004520	10/23/2018	FT-FY19-102018-004520-A	< 1	FT-FY19-102018-004520-B	< 1
WS- 004521	4/13/2018	4/13/2019	1	Cooler	In hallway adjacent to main office 101	WF-04132018-004521	10/23/2018	FT-FY19-102018-004521-A	< 1	FT-FY19-102018-004521-B	< 1
WS- 004522	4/13/2018	4/13/2019	2	Cooler	In hallway adjacent to staff lounge 210	WF-04132018-004522	10/23/2018	FT-FY19-102018-004522-A	< 1	FT-FY19-102018-004522-B	< 1
WS- 004523	4/13/2018	4/13/2019	2	Cooler	In hallway across from stairwell 4	WF-04132018-004523	10/23/2018	FT-FY19-102018-004523-A	< 1	FT-FY19-102018-004523-B	< 1
WS- 004524	4/13/2018	4/13/2019	1	Cooler	In hallway adjacent to room 109	WF-04132018-004524	10/23/2018	FT-FY19-102018-004524-A	< 1	FT-FY19-102018-004524-B	< 1
WS- 004525	4/13/2018	4/13/2019	1	Cooler	In hallway adjacent to ECE boys' room	WF-04132018-004525	10/23/2018	FT-FY19-102018-004525-A	< 1	FT-FY19-102018-004525-B	< 1
WS- 004526	4/13/2018	4/13/2019	2	Cooler	In hallway adjacent to room 201	WF-04132018-004526	10/23/2018	FT-FY19-102018-004526-A	< 1	FT-FY19-102018-004526-B	< 1
WS- 004527	4/13/2018	4/13/2019	2	Cooler	In hallway adjacent to room 203	WF-04132018-004527	10/23/2018	FT-FY19-102018-004527-A	< 1	FT-FY19-102018-004527-B	< 1
WS- 008610	4/13/2018	4/13/2019	1	Cooler	In hallway adjacent to room 104	WF-04132018-008610	10/23/2018	FT-FY19-102018-008610-A	< 1	FT-FY19-102018-008610-B	< 1
WS- 008611	4/13/2018	4/13/2019	1	Cooler	In health suite 107 Left	WF-04132018-008611	10/23/2018	FT-FY19-102018-008611-A	< 1	FT-FY19-102018-008611-B	< 1
WS- 008613	4/13/2018	4/13/2019	1	Break Room	In break room 109	WF-04132018-008613	10/23/2018	FT-FY19-102018-008613-A	< 1	FT-FY19-102018-008613-B	< 1
WS- 008614	4/13/2018	4/13/2019	1	Cooler	In classroom 110	WF-04132018-008614	10/23/2018	FT-FY19-102018-008614-A	< 1	FT-FY19-102018-008614-B	< 1
WS- 008615	4/13/2018	4/13/2019	1	Cooler	In classroom 111	WF-04132018-008615	10/23/2018	FT-FY19-102018-008615-A	< 1	FT-FY19-102018-008615-B	< 1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Floor	Device Type	Device Location			Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 008607	Basement	Food Prep Sink	In kitchen	Left		10/23/2018	FT-FY19-102018-008607-A	1.5	FT-FY19-102018-008607-B	< 1	
WS- 008608	Basement	Food Prep Sink	In kitchen	Right		10/23/2018	FT-FY19-102018-008608-A	< 1	FT-FY19-102018-008608-B	< 1	