



GARRISON LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	GARRISON Elementary School	5/11/2016	WS- 002727	Utility	Basement	In boiler room	WT-042916-2744- A	2.9	WT-042916-2744- B	< 1				
2	GARRISON Elementary School	5/11/2016	WS- 002728	Cooler	1	In hallway adjacent to office room 122	WT-042916-2745- A	< 1	WT-042916-2745- B	< 1				
3	GARRISON Elementary School	5/11/2016	WS- 002729	Cooler	1	In hallway adjacent to custodian supply room	WT-042916-2746- A	< 1	WT-042916-2746- B	< 1				
4	GARRISON Elementary School	5/11/2016	WS- 002730	Cooler	1	In cafeteria adjacent to kitchen entrance	WT-042916-2747- A	< 1	WT-042916-2747- B	< 1				
5	GARRISON Elementary School	5/11/2016	WS- 002731	Kitchen	1	In kitchen west wall	WT-042916-2748- A	< 1	WT-042916-2748- B	< 1				
6	GARRISON Elementary School	5/11/2016	WS- 002732	Kitchen	1	In kitchen north-west wall Right	WT-042916-2749- A	< 1	WT-042916-2749- B	< 1				
7	GARRISON Elementary School	5/11/2016	WS- 002733	Cooler	1	In hallway adjacent to principal's office	WT-042916-2750- A	< 1	WT-042916-2750- B	< 1				
8	GARRISON Elementary School	5/11/2016	WS- 002734	Health Suite	1	In health suite adjacent to bathroom	WT-042916-2751- A	< 1	WT-042916-2751- B	< 1				
9	GARRISON Elementary School	5/11/2016	WS- 002735	Health Suite	1	In health suite adjacent to bathroom (sink faucet)	WT-042916-2752- A	< 1	WT-042916-2752- B	< 1				
10	GARRISON Elementary School	5/11/2016	WS- 002736	Cooler	1	In classroom 110	WT-042916-2753- A	< 1	WT-042916-2753- B	< 1				
11	GARRISON Elementary School	5/11/2016	WS- 002737	Cooler	1	In classroom 109	WT-042916-2754- A	< 1	WT-042916-2754- B	< 1				
12	GARRISON Elementary School	5/11/2016	WS- 002738	Cooler	1	In hallway adjacent to teachers restroom	WT-042916-2755- A	< 1	WT-042916-2755- B	< 1				
13	GARRISON Elementary School	5/11/2016	WS- 002742	Classroom	1	In classroom 110 (hand wash sink) adjacent to cooler	WT-042916-2759- A	< 1	WT-042916-2759- B	< 1				
14	GARRISON Elementary School	5/11/2016	WS- 002743	Classroom	1	Hand wash sink in classroom 109	WT-042916-2760- A	< 1	WT-042916-2760- B	< 1				
15	GARRISON Elementary School	5/11/2016	WS- 002744	Classroom	1	In classroom 106 (hand wash sink)	WT-042916-2761- A	< 1	WT-042916-2761- B	< 1				
16	GARRISON Elementary School	5/11/2016	WS- 002745	Cooler	2	Hallway next to teachers restrooms	WT-042916-2762- A	< 1	WT-042916-2762- B	< 1				
17	GARRISON Elementary School	5/11/2016	WS- 002746	Break Room	1	In teachers breakroom (sink faucet)	WT-042916-2763- A	< 1	WT-042916-2763- B	< 1				
18	GARRISON Elementary School	5/11/2016	WS- 002747	Cooler	2	Hallway adjacent to classroom 201	WT-042916-2764- A	< 1	WT-042916-2764- B	< 1				
19	GARRISON Elementary School	5/11/2016	WS- 002748	Classroom	2	In classroom 201	WT-042916-2765- A	5	WT-042916-2765- B	< 1				
20	GARRISON Elementary School	5/11/2016	WS- 002749	Cooler	2	In hallway adjacent to trash chute -east wing-	WT-042916-2766- A	< 1	WT-042916-2766- B	< 1				
21	GARRISON Elementary School	5/11/2016	WS- 002750	Cooler	2	In hallway adjacent to classroom 217	WT-042916-2767- A	< 1	WT-042916-2767- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.