



GARRISON ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1 GARRISON ELEMENTARY SCHOOL	WS- 002746	12/15/2016	1	Break Room	In staff lounge room 128	FT-112016-002746-A	< 1	FT-112016-002746-B	< 1
2 GARRISON ELEMENTARY SCHOOL	WS- 002742	12/15/2016	1	Classroom Faucet	In classroom 110	FT-122016-002742-A	< 1	FT-122016-002742-B	< 1
3 GARRISON ELEMENTARY SCHOOL	WS- 002743	12/15/2016	1	Classroom Faucet	In classroom 109	FT-122016-002743-A	11	FT-122016-002743-B	< 1
4 GARRISON ELEMENTARY SCHOOL	WS- 009162	12/15/2016	1	Classroom Faucet	In classroom 119	FT-122016-009162-A	3.8	FT-122016-009162-B	< 1
5 GARRISON ELEMENTARY SCHOOL	WS- 002744	12/15/2016	1	Classroom Faucet	In classroom 106	FT-122016-002744-A	14	FT-122016-002744-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

3 GARRISON ELEMENTARY SCHOOL	WS- 002743	1/25/2017	1	Classroom Faucet	In classroom 109	FT-122016-002743-A	< 1	FT-122016-002743-B	< 1
4 GARRISON ELEMENTARY SCHOOL	WS- 009162	1/25/2017	1	Classroom Faucet	In classroom 119	FT-122016-009162-A	< 1	FT-122016-009162-B	< 1
5 GARRISON ELEMENTARY SCHOOL	WS- 002744	1/25/2017	1	Classroom Faucet	In classroom 106	FT-122016-002744-A	< 1	FT-122016-002744-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb