



Hamilton Recreation Center Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006392	3/12/2024	3/12/2025	Ground Floor	Cooler	In hallway adjacent to men's restroom	Low Right	WF-03122024-006392	4/1/2024	FT-FY24-03202024-006392-A	<1	FT-FY24-03202024-006392-B	<1
WS- 006393	3/12/2024	3/12/2025	Ground Floor	Cooler	In hallway adjacent to men's restroom	High Left	WF-03122024-006393	4/1/2024	FT-FY24-03202024-006393-A	<1	FT-FY24-03202024-006393-B	<1