



Hamilton RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006392	4/15/2019	4/15/2020	Ground Floor	Cooler	In hallway adjacent to men's restroom	Low Right	WF-04152019-006392	2/18/2020	FT-FY20-012020-006392-A	<1	FT-FY20-012020-006392-B	<1
WS- 006393	4/15/2019	4/15/2020	Ground Floor	Cooler	In hallway adjacent to men's restroom	High Left	WF-04152019-006393	2/18/2020	FT-FY20-012020-006393-A	<1	FT-FY20-012020-006393-B	<1