



HARDY LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw	
1	HARDY MIDDLE SCHOOL	5/14/2016	WS-010948	Classroom	1	In classroom 102	Right	WT-042916-10965- A	< 1	WT-042916-10965- B	< 1			
2	HARDY MIDDLE SCHOOL	5/14/2016	WS-010906	Cooler	1	In cafeteria	Left High	WT-042916-10923- A	< 1	WT-042916-10923- B	< 1			
3	HARDY MIDDLE SCHOOL	5/14/2016	WS-010905	Classroom	Basement	In boiler room (water source)		WT-042916-10922- A	1.1	WT-042916-10922- B	< 1			
4	HARDY MIDDLE SCHOOL	5/14/2016	WS-010904	Cooler	2	In the gym	Right Low	WT-042916-10921- A	< 1	WT-042916-10921- B	< 1			
5	HARDY MIDDLE SCHOOL	5/14/2016	WS-010903	Cooler	2	In the gym	Left High	WT-042916-10920- A	< 1	WT-042916-10920- B	< 1			
6	HARDY MIDDLE SCHOOL	5/14/2016	WS-010902	Cooler	2	In hallway adjacent to 247	Right Low	WT-042916-10919- A	< 1	WT-042916-10919- B	< 1			
7	HARDY MIDDLE SCHOOL	5/14/2016	WS-010901	Cooler	2	In hallway adjacent to 247	Left High	WT-042916-10918- A	< 1	WT-042916-10918- B	< 1			
8	HARDY MIDDLE SCHOOL	5/14/2016	WS-010900	Classroom	2	In the library 206 work room		WT-042916-10917- A	< 1	WT-042916-10917- B	< 1			
9	HARDY MIDDLE SCHOOL	5/14/2016	WS-010899	Cooler	2	In hallway adjacent to 212	Right Low	WT-042916-10916- A	< 1	WT-042916-10916- B	< 1			
10	HARDY MIDDLE SCHOOL	5/14/2016	WS-010898	Cooler	2	In hallway adjacent to classroom 212	Left High	WT-042916-10915- A	< 1	WT-042916-10915- B	< 1			
11	HARDY MIDDLE SCHOOL	5/14/2016	WS-010897	Classroom	2	In staff lounge 229		WT-042916-10914- A	< 1	WT-042916-10914- B	< 1			
12	HARDY MIDDLE SCHOOL	5/14/2016	WS-010896	Classroom	2	In art lab 226, forth sink clockwise from entry door	Right	WT-042916-10913- A	5.5	WT-042916-10913- B	21.6	Filter will be installed and then retested		
13	HARDY MIDDLE SCHOOL	5/14/2016	WS-010895	Classroom	2	In art lab 226, third sink clockwise from entry door		WT-042916-10912- A	1.3	WT-042916-10912- B	65.8	Filter will be installed and then retested		
14	HARDY MIDDLE SCHOOL	5/14/2016	WS-010894	Classroom	2	In art lab 226, second sink clockwise from entry door		WT-042916-10911- A	1.7	WT-042916-10911- B	332	Filter will be installed and then retested		
15	HARDY MIDDLE SCHOOL	5/14/2016	WS-010893	Classroom	2	In art lab 226, first sink clockwise from entry door	Left	WT-042916-10910- A	< 1	WT-042916-10910- B	6.8			
16	HARDY MIDDLE SCHOOL	5/14/2016	WS-010892	Classroom	2	In art lab 226 (island)	Mid	WT-042916-10909- A	< 1	WT-042916-10909- B	3.7			
17	HARDY MIDDLE SCHOOL	5/14/2016	WS-010891	Classroom	2	In classroom 224, fifth sink clockwise from entry door	Mid	WT-042916-10908- A	< 1	WT-042916-10908- B	4.9			
18	HARDY MIDDLE SCHOOL	5/14/2016	WS-010890	Classroom	2	In classroom 224, forth sink clockwise from entry door	Right	WT-042916-10907- A	9.2	WT-042916-10907- B	11.3			
19	HARDY MIDDLE SCHOOL	5/14/2016	WS-010889	Classroom	2	In classroom 224, third sink clockwise from entry door	Mid	WT-042916-10906- A	< 1	WT-042916-10906- B	81.7	Filter will be installed and then retested		
20	HARDY MIDDLE SCHOOL	5/14/2016	WS-010888	Classroom	2	In classroom 224, second sink clockwise from entry door	Mid	WT-042916-10905- A	1.9	WT-042916-10905- B	56.8	Filter will be installed and then retested		
21	HARDY MIDDLE SCHOOL	5/14/2016	WS-010887	Classroom	2	In classroom 224, first sink clockwise from entry door	Left	WT-042916-10904- A	< 1	WT-042916-10904- B	23.1	Filter will be installed and then retested		
22	HARDY MIDDLE SCHOOL	5/14/2016	WS-010886	Classroom	1	In classroom 130	Mid	WT-042916-10903- A	1.2	WT-042916-10903- B	1			
23	HARDY MIDDLE SCHOOL	5/14/2016	WS-010885	Classroom	1	In classroom 130	Left	WT-042916-10902- A	< 1	WT-042916-10902- B	< 1			
24	HARDY MIDDLE SCHOOL	5/14/2016	WS-010884	Classroom	1	In classroom 130	Right	WT-042916-10901- A	1.1	WT-042916-10901- B	< 1			
25	HARDY MIDDLE SCHOOL	5/14/2016	WS-010883	Classroom	1	In classroom 130		WT-042916-10900- A	< 1	WT-042916-10900- B	< 1			
26	HARDY MIDDLE SCHOOL	5/14/2016	WS-010882	Classroom	1	In teachers L 134		WT-042916-10899- A	< 1	WT-042916-10899- B	< 1			
27	HARDY MIDDLE SCHOOL	5/14/2016	WS-010881	Cooler	1	In hallway adjacent to classroom 119	Right Low	WT-042916-10898- A	< 1	WT-042916-10898- B	< 1			
28	HARDY MIDDLE SCHOOL	5/14/2016	WS-010880	Cooler	1	In hallway adjacent to 119	Left High	WT-042916-10897- A	< 1	WT-042916-10897- B	< 1			
29	HARDY MIDDLE SCHOOL	5/14/2016	WS-010879	Classroom	1	In classroom 140		WT-042916-10896- A	< 1	WT-042916-10896- B	< 1			
30	HARDY MIDDLE SCHOOL	5/14/2016	WS-010878	Classroom	1	In main office 111		WT-042916-10895- A	< 1	WT-042916-10895- B	< 1			
31	HARDY MIDDLE SCHOOL	5/14/2016	WS-010877	Other	1	In kitchen (ice maker)		WT-042916-10894- A	< 1	WT-042916-10894- B	< 1			
32	HARDY MIDDLE SCHOOL	5/14/2016	WS-010876	Kitchen	1	In kitchen sanitation station 04	Right	WT-042916-10893- A	< 1	WT-042916-10893- B	< 1			
33	HARDY MIDDLE SCHOOL	5/14/2016	WS-010875	Kitchen	1	In kitchen Sanitation station rinse	Left	WT-042916-10892- A	1.6	WT-042916-10892- B	< 1			
34	HARDY MIDDLE SCHOOL	5/14/2016	WS-010874	Kitchen	1	In kitchen right side of dishwasher		WT-042916-10891- A	< 1	WT-042916-10891- B	< 1			
35	HARDY MIDDLE SCHOOL	5/14/2016	WS-010873	Kitchen	1	In kitchen adjacent to dry food storage 149		WT-042916-10890- A	2	WT-042916-10890- B	< 1			
36	HARDY MIDDLE SCHOOL	5/14/2016	WS-010872	Kitchen	1	In kitchen adjacent to ice machine		WT-042916-10889- A	< 1	WT-042916-10889- B	< 1			
37	HARDY MIDDLE SCHOOL	5/14/2016	WS-010871	Kitchen	1	In kitchen adjacent to janitor closet 147		WT-042916-10888- A	< 1	WT-042916-10888- B	< 1			
38	HARDY MIDDLE SCHOOL	5/14/2016	WS-010870	Kitchen	1	In kitchen adjacent to janitor closet 143		WT-042916-10887- A	1	WT-042916-10887- B	< 1			
39	HARDY MIDDLE SCHOOL	5/14/2016	WS-010869	Kitchen	1	In cafeteria kitchen mid		WT-042916-10886- A	< 1	WT-042916-10886- B	< 1			



HARDY LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
40 HARDY MIDDLE SCHOOL	5/14/2016	WS-010868	Cooler	1	In cafeteria	WT-042916-10885- A	< 1	WT-042916-10885- B	< 1				
41 HARDY MIDDLE SCHOOL	5/14/2016	WS-010867	Cooler	1	In cafeteria water bottle filler	WT-042916-10884- A	< 1	WT-042916-10884- B	< 1				
42 HARDY MIDDLE SCHOOL	5/14/2016	WS-010866	Classroom	1	In classroom 166	WT-042916-10883- A	< 1	WT-042916-10883- B	< 1				
43 HARDY MIDDLE SCHOOL	5/14/2016	WS-010864	Classroom	1	In classroom 164	WT-042916-10881- A	43.6	WT-042916-10881- B	4.3	Filter will be installed and then retested			
44 HARDY MIDDLE SCHOOL	5/14/2016	WS-010863	Classroom	1	In health suite room 173	WT-042916-10880- A	< 1	WT-042916-10880- B	< 1				
45 HARDY MIDDLE SCHOOL	5/14/2016	WS-010862	Classroom	1	In classroom 101/102	WT-042916-10879- A	< 1	WT-042916-10879- B	< 1				
46 HARDY MIDDLE SCHOOL	5/14/2016	WS-010861	Cooler	1	In hallway adjacent to 167	WT-042916-10878- A	< 1	WT-042916-10878- B	< 1				
47 HARDY MIDDLE SCHOOL	5/14/2016	WS-010860	Cooler	1	In hallway adjacent to 167	WT-042916-10877- A	< 1	WT-042916-10877- B	< 1				
48 HARDY MIDDLE SCHOOL	5/14/2016	WS-010859	Classroom	1	In classroom 105	WT-042916-10876- A	< 1	WT-042916-10876- B	< 1				
49 HARDY MIDDLE SCHOOL	5/14/2016	WS-010858	Classroom	1	In classroom 104	WT-042916-10875- A	< 1	WT-042916-10875- B	< 1				
50 HARDY MIDDLE SCHOOL	5/14/2016	WS-008758	Classroom	3	In classroom 323 (on island)	WT-042916-8775- A	< 1	WT-042916-8775- B	8.8				
51 HARDY MIDDLE SCHOOL	5/14/2016	WS-008757	Classroom	3	In classroom 323 (fourth sink clockwise from door)	WT-042916-8774- A	< 1	WT-042916-8774- B	1.8				
52 HARDY MIDDLE SCHOOL	5/14/2016	WS-008756	Classroom	3	In classroom 323 (third sink clockwise from door)	WT-042916-8773- A	1.2	WT-042916-8773- B	4				
53 HARDY MIDDLE SCHOOL	5/14/2016	WS-008755	Classroom	3	In classroom 323 (second sink clockwise from door)	WT-042916-8772- A	1.1	WT-042916-8772- B	182	Filter will be installed and then retested			
54 HARDY MIDDLE SCHOOL	5/14/2016	WS-008754	Classroom	3	In classroom 323 (first sink clockwise from door)	WT-042916-8771- A	6.1	WT-042916-8771- B	5				
55 HARDY MIDDLE SCHOOL	5/14/2016	WS-008753	Break Room	3	In staff lounge room 327	WT-042916-8770- A	< 1	WT-042916-8770- B	< 1				
56 HARDY MIDDLE SCHOOL	5/14/2016	WS-008752	Classroom	3	In classroom 332 (art room)	WT-042916-8769- A	< 1	WT-042916-8769- B	< 1				
57 HARDY MIDDLE SCHOOL	5/14/2016	WS-008751	Classroom	3	In classroom 332 (art room)	WT-042916-8768- A	< 1	WT-042916-8768- B	< 1				
58 HARDY MIDDLE SCHOOL	5/14/2016	WS-008750	Cooler	3	In hallway (a room from classroom 313)	WT-042916-8767- A	< 1	WT-042916-8767- B	< 1				
59 HARDY MIDDLE SCHOOL	5/14/2016	WS-008749	Cooler	3	In hallway (across from classroom 313)	WT-042916-8766- A	< 1	WT-042916-8766- B	< 1				
60 HARDY MIDDLE SCHOOL	5/14/2016	WS-008748	Classroom	3	In classroom 313	WT-042916-8765- A	< 1	WT-042916-8765- B	< 1				
61 HARDY MIDDLE SCHOOL	5/14/2016	WS-008747	Classroom	3	In classroom 313	WT-042916-8764- A	< 1	WT-042916-8764- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.