



Hardy MS Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008749	4/17/2025	4/17/2026	3	Bottle Filler	In hallway across from room 313	High Left	WF-04172025-008749	11/5/2025	FT-FY26-09302025-008749-A	<2	FT-FY26-09302025-008749-B	<2
WS- 008750	4/17/2025	4/17/2026	3	Cooler	In hallway across from room 313	Low Right	WF-04172025-008750	11/5/2025	FT-FY26-09302025-008750-A	<2	FT-FY26-09302025-008750-B	<2
WS- 008753	4/17/2025	4/17/2026	3	Break Room	In staff lounge 327		WF-04172025-008753	11/5/2025	FT-FY26-09302025-008753-A	<2	FT-FY26-09302025-008753-B	<2
WS- 010860	4/17/2025	4/17/2026	1	Cooler	In hallway adjacent to room 167	High Left	WF-04172025-010860	11/5/2025	FT-FY26-09302025-010860-A	<2	FT-FY26-09302025-010860-B	<2
WS- 010861	4/17/2025	4/17/2026	1	Cooler	In hallway adjacent to room 167	Low Right	WF-04172025-010861	11/5/2025	FT-FY26-09302025-010861-A	<2	FT-FY26-09302025-010861-B	<2
WS- 010863	4/17/2025	4/17/2026	1	Health Suite	In health suite 173		WF-04172025-010863	11/5/2025	FT-FY26-09302025-010863-A	<2	FT-FY26-09302025-010863-B	<2
WS- 010867	4/17/2025	4/17/2026	1	Bottle Filler	In cafeteria (bottle filler)		WF-04172025-010867	11/5/2025	FT-FY26-09302025-010867-A	<2	FT-FY26-09302025-010867-B	<2
WS- 010868	4/17/2025	4/17/2026	1	Cooler	In cafeteria	Low Right	WF-04172025-010868	11/5/2025	FT-FY26-09302025-010868-A	<2	FT-FY26-09302025-010868-B	<2
WS- 010880	4/17/2025	4/17/2026	1	Cooler	In hallway adjacent to room 119	High Left	WF-04172025-010880	11/5/2025	FT-FY26-09302025-010880-A	<2	FT-FY26-09302025-010880-B	<2
WS- 010881	4/17/2025	4/17/2026	1	Cooler	In hallway adjacent to room 119	Low Right	WF-04172025-010881	11/5/2025	FT-FY26-09302025-010881-A	<2	FT-FY26-09302025-010881-B	<2
WS- 010897	4/17/2025	4/17/2026	2	Break Room	In staff lounge 229		WF-04172025-010897	11/5/2025	FT-FY26-09302025-010897-A	<2	FT-FY26-09302025-010897-B	<2
WS- 010898	4/17/2025	4/17/2026	2	Cooler	In hallway adjacent to room 212	High Left	WF-04172025-010898	11/5/2025	FT-FY26-09302025-010898-A	<2	FT-FY26-09302025-010898-B	<2
WS- 010899	4/17/2025	4/17/2026	2	Cooler	In hallway adjacent to room 212	Low Right	WF-04172025-010899	11/5/2025	FT-FY26-09302025-010899-A	<2	FT-FY26-09302025-010899-B	<2
WS- 010901	4/17/2025	4/17/2026	2	Cooler	In hallway adjacent to room 247	High Left	WF-04172025-010901	11/5/2025	FT-FY26-09302025-010901-A	<2	FT-FY26-09302025-010901-B	<2
WS- 010902	4/17/2025	4/17/2026	2	Cooler	In hallway adjacent to room 247	Low Right	WF-04172025-010902	11/5/2025	FT-FY26-09302025-010902-A	<2	FT-FY26-09302025-010902-B	<2
WS- 010903	4/17/2025	4/17/2026	2	Cooler	In gym	High Left	WF-04172025-010903	11/5/2025	FT-FY26-09302025-010903-A	<2	FT-FY26-09302025-010903-B	<2
WS- 010904	4/17/2025	4/17/2026	2	Cooler	In gym	Low Right	WF-04172025-010904	11/5/2025	FT-FY26-09302025-010904-A	<2	FT-FY26-09302025-010904-B	<2
WS- 010906	4/17/2025	4/17/2026	1	Cooler	In cafeteria	High Left	WF-04172025-010906	11/5/2025	FT-FY26-09302025-010906-A	<2	FT-FY26-09302025-010906-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010869	11/25/2024	11/25/2025	1	Food Prep Sink	In kitchen on island		WF-11252024-010869	11/5/2025	FT-FY26-09302025-010869-A	<2	FT-FY26-09302025-010869-B	<2
WS- 010871	11/25/2024	11/25/2025	1	Food Prep Sink	In kitchen adjacent to room 143		WF-11252024-010871	11/5/2025	FT-FY26-09302025-010871-A	<2	FT-FY26-09302025-010871-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.