



# Hardy RC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005515	5/10/2018	5/10/2019	Ground Floor	Bottle Filler	In main lobby adjacent women's restroom (bottle filler)	WF-05102018-005515	2/11/2019	FT-FY19-022019-005515-A	<1	FT-FY19-022019-005515-B	<1
WS- 005516	5/10/2018	5/10/2019	Ground Floor	Cooler	In main lobby adjacent to women's restroom Low	WF-05102018-005516	2/11/2019	FT-FY19-022019-005516-A	<1	FT-FY19-022019-005516-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005517	5/10/2018	5/10/2019	Ground Floor	Food Prep Sink	In kitchenette in main lobby	WF-05102018-005517	2/11/2019	FT-FY19-022019-005517-A	<1	FT-FY19-022019-005517-B	<1