



Hardy RC Lead in Water Test Results

FY22 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005515	10/25/2021	10/25/2022	Ground Floor	Bottle Filler	In main lobby adjacent women's restroom (bottle filler)	WF-10252021-005515	2/15/2022	FT-FY22-01182022-005515-A	<1	FT-FY22-01182022-005515-B	<1
WS- 005516	10/25/2021	10/25/2022	Ground Floor	Cooler	In main lobby adjacent to women's restroom Low	WF-10252021-005516	2/15/2022	FT-FY22-01182022-005516-A	<1	FT-FY22-01182022-005516-B	<1
WS- 005517	10/25/2021	10/25/2022	Ground Floor	Food Prep Sink	In kitchenette in main lobby	WF-10252021-005517	2/15/2022	FT-FY22-01182022-005517-A	<1	FT-FY22-01182022-005517-B	<1