



Hardy RC Lead Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation												
RECORD ID	Filter Installed Date	Filter Expiration	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 005516	6/30/2017	6/30/2018	Ground Floor	Cooler	In main lobby adjacent to women's restroom	Low	WF-62017-005516	1/23/2018	FT-FY18--62017-005516-A	<1	FT-FY18--62017-005516-B	<1

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation												
RECORD ID	Filter Installed Date	Filter Expiration	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 005517	6/30/2017	6/30/2018	Ground Floor	Food Prep Sink	In kitchenette in main lobby		WF-62017-005517	1/23/2018	FT-FY18--62017-005517-A	<1	FT-FY18--62017-005517-B	<1