



Hardy RC Lead in Water Test Results

FY21 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005515	5/18/2020	5/18/2021	Ground Floor	Bottle Filler	In main lobby adjacent women's restroom (bottle filler)	WF-05182020-005515	3/18/2021	FT-FY21-032021-005515-A	<1	FT-FY21-032021-005515-B	<1
WS- 005516	5/18/2020	5/18/2021	Ground Floor	Cooler	In main lobby adjacent to women's restroom Low	WF-05182020-005516	3/18/2021	FT-FY21-032021-005516-A	<1	FT-FY21-032021-005516-B	<1