



Hardy Recreation Center Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-005515	4/15/2024	4/15/2025	Ground Floor	Bottle Filler	In main lobby adjacent women's restroom (bottle filler)	WF-04152024-005515	5/3/2024	FT-FY24-04172024-005515-A	<1	FT-FY24-04172024-005515-B	<1
WS-005516	4/15/2024	4/15/2025	Ground Floor	Cooler	In main lobby adjacent to women's restroom Low	WF-04152024-005516	5/3/2024	FT-FY24-04172024-005516-A	<1	FT-FY24-04172024-005516-B	<1
WS-005517	12/27/2023	12/27/2024	Ground Floor	Food Prep Sink	In kitchenette in main lobby	WF-12272023-005517	5/3/2024	FT-FY24-04172024-005517-A	<1	FT-FY24-04172024-005517-B	<1