



# HARDY REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 HARDY RECREATION CENTER	5/25/2016	WS- 005515	Cooler	Ground Floor	In main lobby adjacent women's restroom water refiller High	WT-042916-5532- A	< 1	WT-042916-5532- B	< 1				
2 HARDY RECREATION CENTER	5/25/2016	WS- 005516	Cooler	Ground Floor	In main lobby adjacent women's restroom Low	WT-042916-5533- A	< 1	WT-042916-5533- B	< 1				
3 HARDY RECREATION CENTER	5/25/2016	WS- 005517	Break Room	Ground Floor	In main lobby near office	WT-042916-5534- A	< 1	WT-042916-5534- B	< 1				
4 HARDY RECREATION CENTER	5/25/2016	WS- 005518	Fountain	Ground Floor	In exterior play area adjacent basketball court Low	WT-042916-5535- A	< 1	WT-042916-5535- B	< 1				
5 HARDY RECREATION CENTER	5/25/2016	WS- 005519	Fountain	Ground Floor	In exterior play area adjacent basketball court High	WT-042916-5536- A	< 1	WT-042916-5536- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.