



# HARRISON REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	HARRISON RECREATION CENTER	5/25/2016	WS- 006133	Fountain	Ground Floor	Exterior adjacent to left side of the building basketball courts Left Low	WT-042916-6150- A	< 1	WT-042916-6150- B	< 1				
2	HARRISON RECREATION CENTER	5/25/2016	WS- 006134	Fountain	Ground Floor	Exterior adjacent to left side of the building and basketball courts Right High	WT-042916-6151- A	< 1	WT-042916-6151- B	< 1				
3	HARRISON RECREATION CENTER	5/25/2016	WS- 006135	Fountain	Ground Floor	Exterior of rec center adjacent to right side of building and baseball field Left Low	WT-042916-6152- A	< 1	WT-042916-6152- B	< 1				
4	HARRISON RECREATION CENTER	5/25/2016	WS- 006136	Fountain	Ground Floor	Exterior of rec center adjacent to right side of building and baseball field Right High	WT-042916-6153- A	< 1	WT-042916-6153- B	< 1				
5	HARRISON RECREATION CENTER	5/25/2016	WS- 006137	Kitchen	1	In rec kitchen area adjacent to janitor closet	WT-042916-6154- A	< 1	WT-042916-6154- B	< 1				
6	HARRISON RECREATION CENTER	5/25/2016	WS- 006138	Cooler	1	In hall adjacent to boys bathroom	WT-042916-6155- A	< 1	WT-042916-6155- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.