



Harry Thomas RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005658	5/17/2018	5/17/2019	2	Bottle Filler	In hallway	WF-05172018-005658	2/25/2019	FT-FY19-022019-005658-A	<1	FT-FY19-022019-005658-B	<1
WS- 005659	5/23/2018	5/23/2019	2	Cooler	In hallway High Right	WF-05232018-005659	2/25/2019	FT-FY19-022019-005659-A	<1	FT-FY19-022019-005659-B	<1
WS- 005661	5/17/2018	5/17/2019	2	Cooler	In hallway Low Left	WF-05172018-005661	2/25/2019	FT-FY19-022019-005661-A	<1	FT-FY19-022019-005661-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005662	5/17/2018	5/17/2019	2	Food Prep Sink	In kitchen	WF-05172018-005662	2/25/2019	FT-FY19-022019-005662-A	<1	FT-FY19-022019-005662-B	<1