



Harry Thomas RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005658	4/9/2019	4/9/2020	2	Bottle Filler	In hallway	WF-04092019-005658	2/25/2020	FT-FY20-012020-005658-A	<1	FT-FY20-012020-005658-B	<1
WS- 005659	4/9/2019	4/9/2020	2	Cooler	In hallway High Right	WF-04092019-005659	2/25/2020	FT-FY20-012020-005659-A	<1	FT-FY20-012020-005659-B	<1
WS- 005661	4/9/2019	4/9/2020	2	Cooler	In hallway Low Left	WF-04092019-005661	2/25/2020	FT-FY20-012020-005661-A	<1	FT-FY20-012020-005661-B	<1
WS- 005662	4/9/2019	4/9/2020	2	Food Prep Sink	In kitchen	WF-04092019-005662	2/25/2020	FT-FY20-012020-005662-A	<1	FT-FY20-012020-005662-B	<1