



HARRY THOMAS SR REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005660	Utility	Basement	In boiler room (water source)	WT-042916-5677- A	< 1	WT-042916-5677- B	< 1				
2	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005661	Cooler	2	In hallway	WT-042916-5678- A	< 1	WT-042916-5678- B	< 1				
3	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005662	Kitchen	2	In kitchen	WT-042916-5679- A	< 1	WT-042916-5679- B	< 1				
4	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005663	Cooler	1	Exterior facing swimming pool	WT-042916-5680- A	< 1	WT-042916-5680- B	< 1				
5	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005664	Fountain	1	Exterior adjacent to basketball court	High WT-042916-5681- A	< 1	WT-042916-5681- B	< 1				
6	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005665	Fountain	1	Exterior adjacent to basketball court	Low WT-042916-5682- A	< 1	WT-042916-5682- B	< 1				
7	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005666	Fountain	1	Exterior in playground	Low WT-042916-5683- A	< 1	WT-042916-5683- B	< 1				
8	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005667	Fountain	1	Exterior in playground	High WT-042916-5684- A	< 1	WT-042916-5684- B	< 1				
9	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005668	Fountain	1	Exterior in basketball court	High WT-042916-5685- A	< 1	WT-042916-5685- B	1				
10	Harry Thomas Sr. Recreation Center	5/25/2016	WS- 005669	Fountain	1	Exterior in basketball court	Low WT-042916-5686- A	< 1	WT-042916-5686- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.