



# HYDE LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010125	Utility	Basement	In water room (Main water source)	WT-042916-10142-A	3.3	WT-042916-10142-B	< 1				
2 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010126	Classroom	2	In classroom 302 Left	WT-042916-10143-A	< 1	WT-042916-10143-B	< 1				
3 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010127	Fountain	2	In classroom 302 Right	WT-042916-10144-A	< 1	WT-042916-10144-B	< 1				
4 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010128	Break Room	2	In break room	WT-042916-10145-A	< 1	WT-042916-10145-B	< 1				
5 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010129	Classroom	2	In classroom 305	WT-042916-10146-A	< 1	WT-042916-10146-B	< 1				
6 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010130	Fountain	2	In classroom 305	WT-042916-10147-A	< 1	WT-042916-10147-B	< 1				
7 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010131	Classroom	2	In classroom 304	WT-042916-10148-A	< 1	WT-042916-10148-B	< 1				
8 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010132	Fountain	2	In classroom 304	WT-042916-10149-A	< 1	WT-042916-10149-B	< 1				
9 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010133	Classroom	2	In classroom 301 Left	WT-042916-10150-A	< 1	WT-042916-10150-B	< 1				
10 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010134	Fountain	2	In classroom 301 Right High	WT-042916-10151-A	< 1	WT-042916-10151-B	< 1				
11 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010135	Classroom	1	In classroom 201 Left	WT-042916-10152-A	< 1	WT-042916-10152-B	< 1				
12 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010136	Fountain	1	In classroom 201 Right	WT-042916-10153-A	< 1	WT-042916-10153-B	< 1				
13 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010137	Classroom	1	In classroom 202	WT-042916-10154-A	< 1	WT-042916-10154-B	< 1				
14 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010138	Fountain	1	In classroom 202	WT-042916-10155-A	< 1	WT-042916-10155-B	< 1				
15 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010139	Classroom	1	In classroom 205 Left	WT-042916-10156-A	< 1	WT-042916-10156-B	< 1				
16 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010140	Fountain	1	In classroom 205 Right	WT-042916-10157-A	< 1	WT-042916-10157-B	< 1				
17 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010141	Health Suite	1	In nursing room	WT-042916-10158-A	< 1	WT-042916-10158-B	< 1				
18 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010142	Classroom	Basement	In room 101 library adjacent to back window Left	WT-042916-10159-A	< 1	WT-042916-10159-B	< 1				
19 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010143	Fountain	Basement	In room 101 library adjacent to the window Right	WT-042916-10160-A	< 1	WT-042916-10160-B	< 1				
20 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010144	Classroom	Basement	In classroom 105 first from left Left	WT-042916-10161-A	1.8	WT-042916-10161-B	< 1				
21 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010145	Classroom	Basement	In classroom 105 second from left	WT-042916-10162-A	< 1	WT-042916-10162-B	< 1				
22 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010146	Classroom	Basement	In classroom 105 third from left	WT-042916-10163-A	< 1	WT-042916-10163-B	< 1				
23 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010147	Classroom	Basement	In classroom 105 last from left	WT-042916-10164-A	< 1	WT-042916-10164-B	< 1				
24 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010148	Classroom	Basement	In classroom 102 Left	WT-042916-10165-A	< 1	WT-042916-10165-B	< 1				
25 HYDE ELEMENTARY SCHOOL	5/10/2016	WS-010149	Fountain	Basement	In classrooms 102	WT-042916-10166-A	< 1	WT-042916-10166-B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.