



Ida B. Wells Middle School Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-015155	4/3/2023	4/3/2024	1	Cooler	In hallway adjacent to 139K restroom	High Left	WF-04032023-015155	11/28/2023	FT-FY24-10102023-015155-A	<1	FT-FY24-10102023-015155-B	<1
WS-015156	4/3/2023	4/3/2024	1	Cooler	In hallway adjacent to 139K restroom	Low Right	WF-04032023-015156	11/28/2023	FT-FY24-10102023-015156-A	<1	FT-FY24-10102023-015156-B	<1
WS-015157	4/3/2023	4/3/2024	1	Cooler	In hallway adjacent to 138 dining (south side)	High Left	WF-04032023-015157	11/28/2023	FT-FY24-10102023-015157-A	<1	FT-FY24-10102023-015157-B	1.3
WS-015158	4/3/2023	4/3/2024	1	Cooler	In hallway adjacent to 138 dining (south side)	Low Right	WF-04032023-015158	11/28/2023	FT-FY24-10102023-015158-A	<1	FT-FY24-10102023-015158-B	<1
WS-015160	4/3/2023	4/3/2024	1	Health Suite	In room 147A		WF-04032023-015160	11/28/2023	FT-FY24-10102023-015160-A	<1	FT-FY24-10102023-015160-B	<1
WS-015226	4/3/2023	4/3/2024	2	Cooler	In hallway adjacent 241	High Left	WF-04032023-015226	11/28/2023	FT-FY24-10102023-015226-A	<1	FT-FY24-10102023-015226-B	<1
WS-015227	4/3/2023	4/3/2024	2	Cooler	In hallway adjacent 241	Low Right	WF-04032023-015227	11/28/2023	FT-FY24-10102023-015227-A	<1	FT-FY24-10102023-015227-B	<1
WS-015236	4/3/2023	4/3/2024	2	Break Room	In room 257		WF-04032023-015236	11/28/2023	FT-FY24-10102023-015236-A	<1	FT-FY24-10102023-015236-B	<1
WS-015266	4/3/2023	4/3/2024	3	Cooler	In room 343		WF-04032023-015266	11/28/2023	FT-FY24-10102023-015266-A	<1	FT-FY24-10102023-015266-B	<1
WS-015267	4/3/2023	4/3/2024	3	Cooler	In hallway adjacent to 345	High Left	WF-04032023-015267	11/28/2023	FT-FY24-10102023-015267-A	<1	FT-FY24-10102023-015267-B	<1
WS-015268	4/3/2023	4/3/2024	3	Cooler	In hallway adjacent to 345	Low Right	WF-04032023-015268	11/28/2023	FT-FY24-10102023-015268-A	<1	FT-FY24-10102023-015268-B	<1
WS-015277	4/3/2023	4/3/2024	3	Break Room	In room 363		WF-04032023-015277	11/28/2023	FT-FY24-10102023-015277-A	<1	FT-FY24-10102023-015277-B	<1
WS-015289	4/3/2023	4/3/2024	4	Cooler	In hallway adjacent to 443	Low Right	WF-04032023-015289	11/28/2023	FT-FY24-10102023-015289-A	<1	FT-FY24-10102023-015289-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-015223	1/3/2023	1/3/2024	2	Food Prep Sink	In room 237		WF-01032023-015223	11/28/2023	FT-FY24-10102023-015223-A	<1	FT-FY24-10102023-015223-B	<1