



INCARCERATED YOUTH LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	Incarcerated Youth Program	5/20/2016	WS- 005497	Utility	1	In pump room BO-128 (main source)	WT-042916-5514- A	52.7	WT-042916-5514- B	8.2	Non-drinking water source - Not accessible to children (boilers)			
2	Incarcerated Youth Program	5/19/2016	WS- 005498	Cooler	Ground Floor	In day room across from cell C4-223	WT-042916-5515- A	< 2	WT-042916-5515- B	< 2				
3	Incarcerated Youth Program	5/20/2016	WS- 005500	Cooler	2	In hallway adjacent to restroom C4A-135	WT-042916-5517- A	< 2	WT-042916-5517- B	< 2				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.