



JANNEY ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service											
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location		1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	JANNEY ELEMENTARY SCHOOL	WS- 002263	12/27/2016	2	Break Room	In staff lounge 212	Right	FT-102016-002263-A	< 1	FT-102016-002263-B	< 1
2	JANNEY ELEMENTARY SCHOOL	WS- 002266	12/27/2016	2	Break Room	In office room 212A in room 212		FT-102016-002266-A	< 1	FT-102016-002266-B	< 1
3	JANNEY ELEMENTARY SCHOOL	WS- 002222	12/27/2016	1	Combo Faucet	In classroom 112	Right	FT-122016-002222-A	< 1	FT-122016-002222-B	< 1
4	JANNEY ELEMENTARY SCHOOL	WS- 002214	12/27/2016	1	Combo Faucet	In classroom 115	Left	FT-122016-002214-A	< 1	FT-122016-002214-B	< 1
5	JANNEY ELEMENTARY SCHOOL	WS- 002231	12/27/2016	1	Combo Faucet	In classroom 106	Left	FT-122016-002231-A	< 1	FT-122016-002231-B	< 1
6	JANNEY ELEMENTARY SCHOOL	WS- 002229	12/27/2016	1	Combo Faucet	In classroom 109	Left	FT-122016-002229-A	< 1	FT-122016-002229-B	< 1
7	JANNEY ELEMENTARY SCHOOL	WS- 002263	12/27/2016	2	Break Room	In staff lounge 212	Right	FT-122016-002263-A	< 1	FT-122016-002263-B	< 1
8	JANNEY ELEMENTARY SCHOOL	WS- 002266	12/27/2016	2	Break Room	In office room 212A in room 212		FT-122016-002266-A	< 1	FT-122016-002266-B	< 1
9	JANNEY ELEMENTARY SCHOOL	WS- 002206	12/27/2016	Basement	Combo Faucet	In classroom L11		FT-122016-002206-A	< 1	FT-122016-002206-B	< 1
10	JANNEY ELEMENTARY SCHOOL	WS- 002212	12/27/2016	1	Combo Faucet	In classroom 117	Left	FT-122016-002212-A	< 1	FT-122016-002212-B	< 1
11	JANNEY ELEMENTARY SCHOOL	WS- 002217	12/27/2016	1	Combo Faucet	In classroom 113	Left	FT-122016-002217-A	< 1	FT-122016-002217-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken											
1	JANNEY ELEMENTARY SCHOOL	WS- 002227	12/27/2016	1	Combo Faucet	In classroom 108	Left	FT-122016-002227-A	< 1	FT-122016-002227-B	1
2	JANNEY ELEMENTARY SCHOOL	WS- 002233	12/27/2016	1	Combo Faucet	In classroom 107	Left	FT-122016-002233-A	< 1	FT-122016-002233-B	7.8

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation											
1	JANNEY ELEMENTARY SCHOOL	WS- 002227	1/25/2017	1	Combo Faucet	In classroom 108	Left	FT-122016-002227-A	1.2	FT-122016-002227-B	< 1
2	JANNEY ELEMENTARY SCHOOL	WS- 002233	1/25/2017	1	Combo Faucet	In classroom 107	Left	FT-122016-002233-A	1.2	FT-122016-002233-B	< 1

Second Filter Re-Test (After Device Replacement)

Less than 1 ppb - Device Returned to Service											
1	JANNEY ELEMENTARY SCHOOL	WS- 002227	4/7/2017	1	Combo Faucet	In classroom 108	Left	FT-122016-002227-A	< 1	FT-122016-002227-B	< 1
2	JANNEY ELEMENTARY SCHOOL	WS- 002233	4/7/2017	1	Combo Faucet	In classroom 107	Left	FT-122016-002233-A	< 1	FT-122016-002233-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb