



# Jefferson MS Lead Water Test Results



## FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-014909	8/7/2019	8/7/2020	Basement	Bottle Filler	In hallway adjacent to room L35 MDF	WF-08072019-014909	8/21/2019	FT-FY20-082019-014909-A	<1	FT-FY20-082019-014909-B	<1
WS-014910	8/7/2019	8/7/2020	Basement	Cooler	In hallway adjacent to room L35 MDF High Left	WF-08072019-014910	8/21/2019	FT-FY20-082019-014910-A	<1	FT-FY20-082019-014910-B	<1
WS-014911	8/7/2019	8/7/2020	Basement	Cooler	In hallway adjacent to room L35 MDF Low Right	WF-08072019-014911	8/21/2019	FT-FY20-082019-014911-A	<1	FT-FY20-082019-014911-B	<1
WS-014912	8/7/2019	8/7/2020	Basement	Break Room	In room L36 teacher collaboration	WF-08072019-014912	8/21/2019	FT-FY20-082019-014912-A	<1	FT-FY20-082019-014912-B	<1
WS-014913	8/7/2019	8/7/2020	Basement	Break Room	In room L16 staff lounge	WF-08072019-014913	8/21/2019	FT-FY20-082019-014913-A	<1	FT-FY20-082019-014913-B	<1
WS-014914	8/7/2019	8/7/2020	Basement	Combo Fountain	In room L16 staff lounge	WF-08072019-014914	8/21/2019	FT-FY20-082019-014914-A	<1	FT-FY20-082019-014914-B	<1
WS-014916	8/7/2019	8/7/2020	1	Combo Fountain	In room 113 reading in 114 office/workroom	WF-08072019-014916	8/21/2019	FT-FY20-082019-014916-A	<1	FT-FY20-082019-014916-B	<1
WS-014917	8/7/2019	8/7/2020	1	Combo Fountain	In room 111 reading in 110 makerspace	WF-08072019-014917	8/21/2019	FT-FY20-082019-014917-A	<1	FT-FY20-082019-014917-B	<1
WS-014920	8/7/2019	8/7/2020	1	Combo Fountain	In room 108 speech/ot/pt	WF-08072019-014920	8/21/2019	FT-FY20-082019-014920-A	<1	FT-FY20-082019-014920-B	<1
WS-014922	8/7/2019	8/7/2020	1	Combo Fountain	In room 119 speech/ot/pt	WF-08072019-014922	8/21/2019	FT-FY20-082019-014922-A	<1	FT-FY20-082019-014922-B	<1
WS-014924	8/7/2019	8/7/2020	1	Combo Fountain	In room 106 speech/ot/pt	WF-08072019-014924	8/21/2019	FT-FY20-082019-014924-A	<1	FT-FY20-082019-014924-B	<1
WS-014925	8/7/2019	8/7/2020	1	Break Room	In room 103 teacher collaboration	WF-08072019-014925	8/21/2019	FT-FY20-082019-014925-A	<1	FT-FY20-082019-014925-B	<1
WS-014927	8/7/2019	8/7/2020	1	Health Suite	In room 127 treatment	WF-08072019-014927	8/21/2019	FT-FY20-082019-014927-A	<1	FT-FY20-082019-014927-B	<1
WS-014928	8/7/2019	8/7/2020	1	Combo Fountain	In room 127 treatment	WF-08072019-014928	8/21/2019	FT-FY20-082019-014928-A	<1	FT-FY20-082019-014928-B	<1
WS-014929	8/7/2019	8/7/2020	1	Bottle Filler	In hallway adjacent to stair D level 1	WF-08072019-014929	8/21/2019	FT-FY20-082019-014929-A	<1	FT-FY20-082019-014929-B	<1
WS-014930	8/7/2019	8/7/2020	1	Cooler	In hallway adjacent to stair D level 1 High Left	WF-08072019-014930	8/21/2019	FT-FY20-082019-014930-A	<1	FT-FY20-082019-014930-B	<1
WS-014931	8/7/2019	8/7/2020	1	Cooler	In hallway adjacent to stair D level 1 Low Right	WF-08072019-014931	8/21/2019	FT-FY20-082019-014931-A	<1	FT-FY20-082019-014931-B	<1
WS-014963	8/7/2019	8/7/2020	2	Combo Fountain	In room 219 classroom	WF-08072019-014963	8/21/2019	FT-FY20-082019-014963-A	<1	FT-FY20-082019-014963-B	<1
WS-014964	8/7/2019	8/7/2020	2	Break Room	In room 222	WF-08072019-014964	8/21/2019	FT-FY20-082019-014964-A	<1	FT-FY20-082019-014964-B	<1
WS-014966	8/7/2019	8/7/2020	3	Combo Fountain	In room 305 classroom	WF-08072019-014966	8/21/2019	FT-FY20-082019-014966-A	<1	FT-FY20-082019-014966-B	<1
WS-014967	8/7/2019	8/7/2020	3	Bottle Filler	In hallway across from stair B level 3	WF-08072019-014967	8/21/2019	FT-FY20-082019-014967-A	<1	FT-FY20-082019-014967-B	<1
WS-014968	8/7/2019	8/7/2020	3	Cooler	In hallway across from stair B level 3 High Left	WF-08072019-014968	8/21/2019	FT-FY20-082019-014968-A	<1	FT-FY20-082019-014968-B	<1
WS-014969	8/7/2019	8/7/2020	3	Cooler	In hallway across from stair B level 3 Low Right	WF-08072019-014969	8/21/2019	FT-FY20-082019-014969-A	<1	FT-FY20-082019-014969-B	<1
WS-014975	8/7/2019	8/7/2020	1	Bottle Filler	In room 113 reading room	WF-08072019-014975	8/21/2019	FT-FY20-082019-014975-A	<1	FT-FY20-082019-014975-B	<1
WS-014976	8/7/2019	8/7/2020	1	Cooler	In room 113 reading room High Left	WF-08072019-014976	8/21/2019	FT-FY20-082019-014976-A	<1	FT-FY20-082019-014976-B	<1
WS-014977	8/7/2019	8/7/2020	1	Cooler	In room 113 reading room Low Right	WF-08072019-014977	8/21/2019	FT-FY20-082019-014977-A	<1	FT-FY20-082019-014977-B	<1
WS-014978	8/7/2019	8/7/2020	2	Bottle Filler	In hallway adjacent to room 203	WF-08072019-014978	8/21/2019	FT-FY20-082019-014978-A	<1	FT-FY20-082019-014978-B	<1
WS-014979	8/7/2019	8/7/2020	2	Cooler	In hallway adjacent to room 203 High Left	WF-08072019-014979	8/21/2019	FT-FY20-082019-014979-A	<1	FT-FY20-082019-014979-B	<1
WS-014980	8/7/2019	8/7/2020	2	Cooler	In hallway adjacent to room 203 Low Right	WF-08072019-014980	8/21/2019	FT-FY20-082019-014980-A	<1	FT-FY20-082019-014980-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-014902	8/7/2019	8/7/2020	Basement	Food Prep Sink	In kitchen third clockwise from entry	WF-08072019-014902	8/21/2019	FT-FY20-082019-014902-A	<1	FT-FY20-082019-014902-B	<1