



# JELLEFF REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	JELLEFF RECREATION CENTER	5/26/2016	WS- 006140	Kitchen	1	In kitchen (water source) Left	WT-042916-6157- A	< 1	WT-042916-6157- B	< 1				
2	JELLEFF RECREATION CENTER	5/26/2016	WS- 006141	Kitchen	1	In kitchen (water source) Right	WT-042916-6158- A	< 1	WT-042916-6158- B	< 1				
3	JELLEFF RECREATION CENTER	5/26/2016	WS- 006142	Cooler	1	In hallway adjacent to boys bathroom	WT-042916-6159- A	< 1	WT-042916-6159- B	< 1				
4	JELLEFF RECREATION CENTER	5/26/2016	WS- 006143	Cooler	2	In hallway adjacent to boys locker room	WT-042916-6160- A	< 1	WT-042916-6160- B	< 1				
5	JELLEFF RECREATION CENTER	5/26/2016	WS- 006144	Fountain	Ground Floor	Outside near pool area Low	WT-042916-6161- A	< 1	WT-042916-6161- B	< 1				
6	JELLEFF RECREATION CENTER	5/26/2016	WS- 006145	Fountain	Ground Floor	Outside near pool area High	WT-042916-6162- A	< 1	WT-042916-6162- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.