



# Jelleff RC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006142	4/11/2018	4/11/2019	1	Cooler	In hallway adjacent to boys' restroom	WF-04112018-006142	1/25/2019	FT-FY19-012019-006142-A	<1	FT-FY19-012019-006142-B	<1
WS- 006143	4/26/2018	4/26/2019	2	Cooler	In hallway adjacent to boys' locker room	WF-04262018-006143	1/25/2019	FT-FY19-012019-006143-A	<1	FT-FY19-012019-006143-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006140	4/11/2018	4/11/2019	1	Food Prep Sink	In kitchen (water source) Left	WF-04112018-006140	1/25/2019	FT-FY19-012019-006140-A	<1	FT-FY19-012019-006140-B	<1
WS- 006141	4/11/2018	4/11/2019	1	Food Prep Sink	In kitchen Right	WF-04112018-006141	1/25/2019	FT-FY19-012019-006141-A	<1	FT-FY19-012019-006141-B	<1