



Johnson MS Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 002324	5/29/2018	5/29/2019	4	Cooler	In hallway across from room 420	WF-05292018-002324	12/18/2018	FT-FY19-122018-002324-A	<1	FT-FY19-122018-002324-B	<1	
WS- 002325	5/29/2018	5/29/2019	4	Cooler	In hallway adjacent to room 416	WF-05292018-002325	12/18/2018	FT-FY19-122018-002325-A	<1	FT-FY19-122018-002325-B	<1	
WS- 010550	5/29/2018	5/29/2019	Ground Floor	Cooler	In rec room adjacent to cafeteria	WF-05292018-010550	12/18/2018	FT-FY19-122018-010550-A	<1	FT-FY19-122018-010550-B	<1	
WS- 011105	12/6/2018	12/6/2019	Ground Floor	Food Prep Sink	In kitchen third clockwise from entry door	WF-12062018-011105	12/18/2018	FT-FY19-122018-011105-A	<1	FT-FY19-122018-011105-B	<1	
WS- 011109	5/29/2018	5/29/2019	Ground Floor	Ice Maker	In kitchen (ice maker)	WF-05292018-011109	12/18/2018	FT-FY19-122018-011109-A	<1	FT-FY19-122018-011109-B	<1	
WS- 011110	5/29/2018	5/29/2019	Ground Floor	Cooler	In cafeteria east wall	WF-05292018-011110	12/18/2018	FT-FY19-122018-011110-A	<1	FT-FY19-122018-011110-B	<1	
WS- 011111	5/29/2018	5/29/2019	Ground Floor	Cooler	In cafeteria west wall	WF-05292018-011111	12/18/2018	FT-FY19-122018-011111-A	<1	FT-FY19-122018-011111-B	<1	
WS- 011113	5/29/2018	5/29/2019	1	Health Suite	In health suite in treatment room 111B	WF-05292018-011113	12/18/2018	FT-FY19-122018-011113-A	<1	FT-FY19-122018-011113-B	<1	
WS- 011115	5/29/2018	5/29/2019	1	Break Room	In break room 107	WF-05292018-011115	12/18/2018	FT-FY19-122018-011115-A	<1	FT-FY19-122018-011115-B	<1	
WS- 011116	5/29/2018	5/29/2019	1	Cooler	In hallway adjacent to room 111	WF-05292018-011116	12/18/2018	FT-FY19-122018-011116-A	<1	FT-FY19-122018-011116-B	<1	
WS- 011117	5/29/2018	5/29/2019	1	Cooler	In hallway adjacent to auditorium	WF-05292018-011117	12/18/2018	FT-FY19-122018-011117-A	<1	FT-FY19-122018-011117-B	<1	
WS- 011118	5/29/2018	5/29/2019	1	Cooler	In girls' locker room	WF-05292018-011118	12/18/2018	FT-FY19-122018-011118-A	<1	FT-FY19-122018-011118-B	<1	
WS- 011121	5/29/2018	5/29/2019	2	Cooler	In hallway adjacent to room 204	WF-05292018-011121	12/18/2018	FT-FY19-122018-011121-A	<1	FT-FY19-122018-011121-B	<1	
WS- 011122	5/29/2018	5/29/2019	2	Cooler	In hallway adjacent to room 220	High Left	WF-05292018-011122	12/18/2018	FT-FY19-122018-011122-A	<1	FT-FY19-122018-011122-B	<1
WS- 011123	5/29/2018	5/29/2019	2	Cooler	In hallway adjacent to room 220	Low Right	WF-05292018-011123	12/18/2018	FT-FY19-122018-011123-A	<1	FT-FY19-122018-011123-B	<1
WS- 011133	5/29/2018	5/29/2019	3	Cooler	In hallway adjacent to room 318	High Left	WF-05292018-011133	12/18/2018	FT-FY19-122018-011133-A	<1	FT-FY19-122018-011133-B	<1
WS- 011134	5/29/2018	5/29/2019	3	Cooler	In hallway adjacent to room 318	Low Right	WF-05292018-011134	12/18/2018	FT-FY19-122018-011134-A	<1	FT-FY19-122018-011134-B	<1
WS- 011144	5/29/2018	5/29/2019	3	Cooler	In hallway adjacent to room 312	High Left	WF-05292018-011144	12/18/2018	FT-FY19-122018-011144-A	<1	FT-FY19-122018-011144-B	<1
WS- 011145	5/29/2018	5/29/2019	3	Cooler	In hallway adjacent to room 312	Low Right	WF-05292018-011145	12/18/2018	FT-FY19-122018-011145-A	<1	FT-FY19-122018-011145-B	<1
WS- 011146	5/29/2018	5/29/2019	3	Cooler	In hallway adjacent to room 302		WF-05292018-011146	12/18/2018	FT-FY19-122018-011146-A	<1	FT-FY19-122018-011146-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation									
Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 011105	Ground Floor	Food Prep Sink	In kitchen third clockwise from entry door	12/18/2018	FT-FY19-122018-011105-A	<1	FT-FY19-122018-011105-B	<1	