



JOSEPH H COLE REC LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 JOSEPH H COLE RECREATION CENTER	5/26/2016	WS- 005520	Cooler	1	In main hallway between men's and women's restroom High	WT-042916-5537- A	< 1	WT-042916-5537- B	< 1				
2 JOSEPH H COLE RECREATION CENTER	5/26/2016	WS- 005521	Cooler	1	In main hallway between men's and women's restroom Low	WT-042916-5538- A	< 1	WT-042916-5538- B	< 1				
3 JOSEPH H COLE RECREATION CENTER	5/26/2016	WS- 005522	Classroom	1	In room G134	WT-042916-5539- A	< 1	WT-042916-5539- B	< 1				
4 JOSEPH H COLE RECREATION CENTER	5/26/2016	WS- 005523	Break Room	1	In multipurpose room G131/132	WT-042916-5540- A	< 1	WT-042916-5540- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.