



# Kalorama RC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

| Record ID  | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location                      |      |       | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID    | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID    | FT Final Result - 2nd Draw (ppb) |
|------------|-----------------------|------------------------|-------|-------------|--------------------------------------|------|-------|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| WS- 012692 | 5/4/2018              | 5/4/2019               | 1     | Cooler      | In hallway adjacent to main entrance | High | Left  | WF-05042018-012692  | 2/4/2019      | FT-FY19-012019-012692-A | <1                               | FT-FY19-012019-012692-B | <1                               |
| WS- 012693 | 5/4/2018              | 5/4/2019               | 1     | Cooler      | In hallway adjacent to main entrance | Low  | Right | WF-05042018-012693  | 2/4/2019      | FT-FY19-012019-012693-A | <1                               | FT-FY19-012019-012693-B | <1                               |