



# KELLY MILLER LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009789	Classroom	1	In first floor assistant principals office A126	WT-042916-9806- A	< 1	WT-042916-9806- B	< 1			
2	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009788	Classroom	1	In first floor special education office A127	WT-042916-9805- A	< 1	WT-042916-9805- B	< 1			
3	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009787	Classroom	1	In workroom B116	WT-042916-9804- A	< 1	WT-042916-9804- B	< 1			
4	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009786	Health Suite	1	In health room B111	WT-042916-9803- A	< 1	WT-042916-9803- B	< 1			
5	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009785	Kitchen	1	In kitchen across from D106	WT-042916-9802- A	< 1	WT-042916-9802- B	< 1			
6	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009784	Kitchen	1	In kitchen across from D110 (icemaker)	WT-042916-9801- A	< 1	WT-042916-9801- B	< 1			
7	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009782	Classroom	2	In second floor workroom A226	WT-042916-9799- A	< 1	WT-042916-9799- B	< 1			
8	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009781	Classroom	3	In workroom A327	WT-042916-9798- A	< 1	WT-042916-9798- B	< 1			
9	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009780	Classroom	2	In second floor workroom A227	WT-042916-9797- A	< 1	WT-042916-9797- B	< 1			
10	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009779	Classroom	3	In workroom A325	WT-042916-9796- A	< 1	WT-042916-9796- B	< 1			
11	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009778	Classroom	3	In classroom A306 clockwise from eye wash (8)	WT-042916-9795- A	124	WT-042916-9795- B	8.5	Filter will be installed and then retested		
12	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009777	Classroom	3	In classroom A306 clockwise from eye wash (7)	WT-042916-9794- A	6.2	WT-042916-9794- B	< 1			
13	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009776	Classroom	3	In classroom A306 clockwise from eye wash (6)	WT-042916-9793- A	171	WT-042916-9793- B	1.7	Filter will be installed and then retested		
14	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009775	Classroom	3	In classroom A306 clockwise from eye wash (5)	WT-042916-9792- A	22.9	WT-042916-9792- B	1.8	Filter will be installed and then retested		
15	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009774	Classroom	3	In classroom A306 clockwise from eye wash (4)	WT-042916-9791- A	74.9	WT-042916-9791- B	2.5	Filter will be installed and then retested		
16	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009773	Classroom	3	In classroom A306 clockwise from eye wash (3)	WT-042916-9790- A	21.1	WT-042916-9790- B	1.1	Filter will be installed and then retested		
17	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009772	Classroom	3	In classroom A306 clockwise from eye wash (2)	WT-042916-9789- A	19.8	WT-042916-9789- B	1	Filter will be installed and then retested		
18	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009771	Classroom	3	In classroom A306 clockwise from eye wash (1)	WT-042916-9788- A	9.9	WT-042916-9788- B	< 1			
19	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009770	Classroom	3	In vestibule (A304-A306)	WT-042916-9787- A	3.4	WT-042916-9787- B	< 1			
20	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009769	Classroom	3	In classroom A304 counterclockwise from eye wash (8)	WT-042916-9786- A	< 1	WT-042916-9786- B	< 1			
21	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009768	Classroom	3	In classroom A304 counterclockwise from eye wash (7)	WT-042916-9785- A	13.4	WT-042916-9785- B	1			
22	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009767	Classroom	3	In classroom A304 counterclockwise from eye wash (6)	WT-042916-9784- A	22	WT-042916-9784- B	< 1			
23	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009766	Classroom	3	In classroom A304 counterclockwise from eyewash(5)	WT-042916-9783- A	63.8	WT-042916-9783- B	4.9	Filter will be installed and then retested		
24	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009765	Classroom	3	In classroom A304 counterclockwise from eye wash (4)	WT-042916-9782- A	10.1	WT-042916-9782- B	1.8			
25	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009764	Classroom	3	In classroom A304 counterclockwise from eye wash (3)	WT-042916-9781- A	11	WT-042916-9781- B	1.5			
26	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009763	Classroom	3	In classroom A304 counterclockwise from eye wash (2)	WT-042916-9780- A	18	WT-042916-9780- B	< 1	Filter will be installed and then retested		
27	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009762	Classroom	3	In classroom A304 counterclockwise from eye wash (1)	WT-042916-9779- A	10.9	WT-042916-9779- B	< 1			



# KELLY MILLER LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
28	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009761	Cooler	3	In third floor hallway adjacent to elevator	Low	WT-042916-9778- A	< 1	WT-042916-9778- B	< 1		
29	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009760	Cooler	3	In third floor hallway adjacent to elevator	High	WT-042916-9777- A	< 1	WT-042916-9777- B	< 1		
30	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009759	Cooler	3	In hallway adjacent to boys room	Low	WT-042916-9776- A	< 1	WT-042916-9776- B	< 1		
31	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009758	Cooler	3	In hallway adjacent to boys room	High	WT-042916-9775- A	< 1	WT-042916-9775- B	< 1		
32	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009757	Classroom	1	In vestibule (A104-A106)		WT-042916-9774- A	116	WT-042916-9774- B	7.4	Filter will be installed and then retested	
33	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009756	Classroom	2	In vestibule (A204-A206)		WT-042916-9773- A	2.1	WT-042916-9773- B	< 1		
34	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009755	Classroom	2	In classroom A206 clockwise from eye wash (8)		WT-042916-9772- A	8.3	WT-042916-9772- B	12.7		
35	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009754	Classroom	2	In classroom A206 clockwise from eye wash (7)		WT-042916-9771- A	11.7	WT-042916-9771- B	< 1		
36	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009753	Classroom	2	In classroom A206 clockwise from eye wash (6)		WT-042916-9770- A	141	WT-042916-9770- B	1.4	Filter will be installed and then retested	
37	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009752	Classroom	2	In classroom A206 clockwise from eye wash (5)		WT-042916-9769- A	18.2	WT-042916-9769- B	< 1	Filter will be installed and then retested	
38	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009751	Classroom	2	In classroom A206 clockwise from eye wash (4)		WT-042916-9768- A	7.4	WT-042916-9768- B	< 1		
39	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009750	Classroom	2	In classroom A206 clockwise from eye wash (3)		WT-042916-9767- A	3.3	WT-042916-9767- B	< 1		
40	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009749	Classroom	2	In classroom A206 clockwise from eye wash (2)		WT-042916-9766- A	1	WT-042916-9766- B	6.3		
41	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009748	Classroom	2	In classroom A206 clockwise from eye wash (1)		WT-042916-9765- A	3.5	WT-042916-9765- B	< 1		
42	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009747	Classroom	2	In classroom A204 counterclockwise from eye wash (8)		WT-042916-9764- A	11.7	WT-042916-9764- B	25.9	Filter will be installed and then retested	
43	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009746	Classroom	2	In classroom A204 counterclockwise from eye wash (1)		WT-042916-9763- A	< 1	WT-042916-9763- B	< 1		
44	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009745	Classroom	2	In classroom A204 counterclockwise from eye wash (2)		WT-042916-9762- A	69.7	WT-042916-9762- B	84.1	Filter will be installed and then retested	
45	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009744	Classroom	2	In classroom A204 counterclockwise from eye wash (3)		WT-042916-9761- A	1.5	WT-042916-9761- B	< 1		
46	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009743	Classroom	2	In classroom A204 counterclockwise from eye wash (4)		WT-042916-9760- A	< 1	WT-042916-9760- B	< 1		
47	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009742	Classroom	2	In classroom A204 counterclockwise from eye wash (5)		WT-042916-9759- A	< 1	WT-042916-9759- B	< 1		
48	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009741	Classroom	2	In classroom A204 counterclockwise from eye wash (6)		WT-042916-9758- A	5.9	WT-042916-9758- B	4.7		
49	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009740	Classroom	2	In classroom A204 counterclockwise from eye wash (7)		WT-042916-9757- A	< 1	WT-042916-9757- B	< 1		
50	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009739	Break Room	2	In teachers lounge kitchen		WT-042916-9756- A	< 1	WT-042916-9756- B	< 1		
51	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009738	Cooler	2	In hallway adjacent to elevator	Low	WT-042916-9755- A	< 1	WT-042916-9755- B	< 1		
52	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009737	Cooler	2	In hallway adjacent to elevator	High	WT-042916-9754- A	< 1	WT-042916-9754- B	< 1		
53	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009736	Cooler	2	In hallway next to room A218	Low	WT-042916-9753- A	< 1	WT-042916-9753- B	< 1		
54	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009735	Cooler	2	In hallway next to room A218	High	WT-042916-9752- A	< 1	WT-042916-9752- B	< 1		
55	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009734	Cooler	1	In hallway across from lan room C123	High	WT-042916-9751- A	< 1	WT-042916-9751- B	< 1		
56	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009733	Cooler	1	In hallway across from lan room C123	Low	WT-042916-9750- A	< 1	WT-042916-9750- B	< 1		
57	KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS- 009732	Classroom	1	In classroom A104 counterclockwise from eye wash (8)		WT-042916-9749- A	17.9	WT-042916-9749- B	13.4	Filter will be installed and then retested	



# KELLY MILLER LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
58 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009731	Classroom	1	In classroom A104 counterclockwise from eye wash (7)	WT-042916-9748- A	146	WT-042916-9748- B	3.8	Filter will be installed and then retested			
59 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009730	Classroom	1	In classroom A104 counterclockwise from eye wash (6)	WT-042916-9747- A	9.3	WT-042916-9747- B	2				
60 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009729	Classroom	1	In classroom A104 counterclockwise from eye wash (5)	WT-042916-9746- A	< 1	WT-042916-9746- B	< 1				
61 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009728	Classroom	1	In classroom A104 counterclockwise from eye wash (4)	WT-042916-9745- A	< 1	WT-042916-9745- B	< 1				
62 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009727	Classroom	1	In classroom A104 counterclockwise from eye wash (3)	WT-042916-9744- A	< 1	WT-042916-9744- B	< 1				
63 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009726	Classroom	1	In classroom A104 counterclockwise from eye wash (2)	WT-042916-9743- A	1	WT-042916-9743- B	< 1				
64 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009725	Classroom	1	In classroom A104 counterclockwise from eye wash (1)	WT-042916-9742- A	< 1	WT-042916-9742- B	< 1				
65 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009724	Classroom	1	In room A106 clockwise from eye wash (8)	WT-042916-9741- A	29	WT-042916-9741- B	2.6	Filter will be installed and then retested			
66 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009723	Classroom	1	In room A106 clockwise from eye wash (7)	WT-042916-9740- A	3.7	WT-042916-9740- B	< 1				
67 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009722	Classroom	1	In room A106 clockwise from eye wash (6)	WT-042916-9739- A	30.1	WT-042916-9739- B	1.2	Filter will be installed and then retested			
68 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009721	Classroom	1	In room A106 clockwise from eye wash (5)	WT-042916-9738- A	7.8	WT-042916-9738- B	< 1				
69 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009720	Classroom	1	In room A106 clockwise from eye wash (4)	WT-042916-9737- A	8.5	WT-042916-9737- B	< 1				
70 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009719	Classroom	1	In room A106 clockwise from eye wash (3)	WT-042916-9736- A	10.1	WT-042916-9736- B	< 1				
71 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009718	Classroom	1	In room A106 clockwise from eye wash (2)	WT-042916-9735- A	46	WT-042916-9735- B	1.2	Filter will be installed and then retested			
72 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009717	Cooler	1	In gymnasium adjacent to girls locker room	WT-042916-9734- A	< 1	WT-042916-9734- B	< 1				
73 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009716	Cooler	1	In gymnasium adjacent to D122	WT-042916-9733- A	< 1	WT-042916-9733- B	< 1				
74 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009714	Classroom	1	In room A106 clockwise from eye wash (1)	WT-042916-9731- A	3.8	WT-042916-9731- B	< 1				
75 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009712	Cooler	1	In first floor hallway adjacent to room A118	Low	WT-042916-9729- A	< 1	WT-042916-9729- B	< 1			
76 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009711	Cooler	1	In first floor hallway adjacent to room A118	High	WT-042916-9728- A	< 1	WT-042916-9728- B	< 1			
77 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009710	Cooler	1	In first floor hallway adjacent to elevator	Low	WT-042916-9727- A	< 1	WT-042916-9727- B	< 1			
78 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009709	Cooler	1	In first floor hallway adjacent to elevator	High	WT-042916-9726- A	< 1	WT-042916-9726- B	< 1			
79 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009706	Kitchen	1	In kitchen across from freezer D114	WT-042916-9723- A	< 1	WT-042916-9723- B	< 1				
80 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009705	Kitchen	1	In kitchen adjacent to storage room	Right	WT-042916-9722- A	< 1	WT-042916-9722- B	< 1			
81 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009704	Kitchen	1	In kitchen adjacent to storage room	Mid	WT-042916-9721- A	< 1	WT-042916-9721- B	< 1			
82 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009703	Kitchen	1	In kitchen adjacent to storage room (spray nozzle)	Left	WT-042916-9720- A	< 1	WT-042916-9720- B	2.9			
83 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009702	Cooler	1	In cafeteria adjacent to kitchen	WT-042916-9719- A	< 1	WT-042916-9719- B	< 1				
84 KELLY MILLER MIDDLE SCHOOL	5/14/2016	WS-009701	Utility	1	In boiler room	WT-042916-9718- A	3.1	WT-042916-9718- B	1.7				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.