



Kelly Miller Middle School Lead in Water Test Results

FY21 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009702	3/9/2021	3/9/2022	1	Cooler	In cafeteria	WF-03092021-009702	5/4/2021	FT-FY21-042021-009702-A	<1	FT-FY21-042021-009702-B	<1
WS-009709	3/9/2021	3/9/2022	1	Cooler	In hallway adjacent to elevator High Left	WF-03092021-009709	5/4/2021	FT-FY21-042021-009709-A	<1	FT-FY21-042021-009709-B	<1
WS-009710	3/9/2021	3/9/2022	1	Cooler	In hallway adjacent to elevator Low Right	WF-03092021-009710	5/4/2021	FT-FY21-042021-009710-A	<1	FT-FY21-042021-009710-B	<1
WS-009711	3/9/2021	3/9/2022	1	Cooler	In hallway adjacent to room A118 High Left	WF-03092021-009711	5/4/2021	FT-FY21-042021-009711-A	<1	FT-FY21-042021-009711-B	<1
WS-009712	3/9/2021	3/9/2022	1	Cooler	In hallway adjacent to room A118 Low Right	WF-03092021-009712	5/4/2021	FT-FY21-042021-009712-A	<1	FT-FY21-042021-009712-B	<1
WS-009717	3/9/2021	3/9/2022	1	Cooler	In gym adjacent to girls' locker room	WF-03092021-009717	5/4/2021	FT-FY21-042021-009717-A	<1	FT-FY21-042021-009717-B	<1
WS-009733	3/9/2021	3/9/2022	1	Cooler	In hallway across from room C123 Low Left	WF-03092021-009733	5/4/2021	FT-FY21-042021-009733-A	<1	FT-FY21-042021-009733-B	2.0
WS-009734	3/9/2021	3/9/2022	1	Cooler	In hallway across from room C123 High Right	WF-03092021-009734	5/4/2021	FT-FY21-042021-009734-A	<1	FT-FY21-042021-009734-B	<1
WS-009735	3/9/2021	3/9/2022	2	Cooler	In hallway adjacent to room A218 High Left	WF-03092021-009735	5/4/2021	FT-FY21-042021-009735-A	<1	FT-FY21-042021-009735-B	<1
WS-009736	3/9/2021	3/9/2022	2	Cooler	In hallway adjacent to room A218 Low Right	WF-03092021-009736	5/4/2021	FT-FY21-042021-009736-A	<1	FT-FY21-042021-009736-B	<1
WS-009737	3/9/2021	3/9/2022	2	Cooler	In hallway adjacent to elevator High Left	WF-03092021-009737	5/4/2021	FT-FY21-042021-009737-A	<1	FT-FY21-042021-009737-B	<1
WS-009738	3/9/2021	3/9/2022	2	Cooler	In hallway adjacent to elevator Low Right	WF-03092021-009738	5/4/2021	FT-FY21-042021-009738-A	<1	FT-FY21-042021-009738-B	<1
WS-009739	3/9/2021	3/9/2022	2	Break Room	In staff lounge kitchen	WF-03092021-009739	5/4/2021	FT-FY21-042021-009739-A	<1	FT-FY21-042021-009739-B	<1
WS-009760	3/9/2021	3/9/2022	3	Cooler	In hallway adjacent to elevator High Right	WF-03092021-009760	5/4/2021	FT-FY21-042021-009760-A	<1	FT-FY21-042021-009760-B	<1
WS-009761	3/9/2021	3/9/2022	3	Cooler	In hallway adjacent to elevator Low Left	WF-03092021-009761	5/4/2021	FT-FY21-042021-009761-A	<1	FT-FY21-042021-009761-B	<1
WS-009780	3/9/2021	3/9/2022	2	Break Room	In workroom A227	WF-03092021-009780	5/4/2021	FT-FY21-042021-009780-A	<1	FT-FY21-042021-009780-B	<1
WS-009782	3/9/2021	3/9/2022	2	Break Room	In workroom A226	WF-03092021-009782	5/4/2021	FT-FY21-042021-009782-A	<1	FT-FY21-042021-009782-B	<1
WS-009786	3/9/2021	3/9/2022	1	Health Suite	In health suite B112	WF-03092021-009786	5/4/2021	FT-FY21-042021-009786-A	<1	FT-FY21-042021-009786-B	<1
WS-009787	3/9/2021	3/9/2022	1	Break Room	In workroom B116	WF-03092021-009787	5/4/2021	FT-FY21-042021-009787-A	<1	FT-FY21-042021-009787-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009706	2/22/2021	2/22/2022	1	Food Prep Sink	In kitchen across from room D114	WF-02222021-009706	5/4/2021	FT-FY21-042021-009706-A	<1	FT-FY21-042021-009706-B	<1