



Kelly Miller Middle School Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 009702	2/28/2022	2/28/2023	1	Cooler	In cafeteria	WF-02282022-009702	1/26/2023	FT-FY23-01102023-009702-A	<1	FT-FY23-01102023-009702-B	<1	
WS- 009708	2/28/2022	2/28/2023	1	Bottle Filler	In cafeteria	WF-02282022-009708	1/26/2023	FT-FY23-01102023-009708-A	<1	FT-FY23-01102023-009708-B	<1	
WS- 009717	2/28/2022	2/28/2023	1	Cooler	In gym adjacent to girls' locker room	WF-02282022-009717	1/26/2023	FT-FY23-01102023-009717-A	<1	FT-FY23-01102023-009717-B	<1	
WS- 009733	2/28/2022	2/28/2023	1	Cooler	In hallway across from room C123	Low Left	WF-02282022-009733	1/26/2023	FT-FY23-01102023-009733-A	<1	FT-FY23-01102023-009733-B	<1
WS- 009734	2/28/2022	2/28/2023	1	Cooler	In hallway across from room C123	High Right	WF-02282022-009734	1/26/2023	FT-FY23-01102023-009734-A	<1	FT-FY23-01102023-009734-B	<1
WS- 009735	2/28/2022	2/28/2023	2	Cooler	In hallway adjacent to room A218	High Left	WF-02282022-009735	1/26/2023	FT-FY23-01102023-009735-A	<1	FT-FY23-01102023-009735-B	<1
WS- 009736	2/28/2022	2/28/2023	2	Cooler	In hallway adjacent to room A218	Low Right	WF-02282022-009736	1/26/2023	FT-FY23-01102023-009736-A	<1	FT-FY23-01102023-009736-B	<1
WS- 009737	2/28/2022	2/28/2023	2	Cooler	In hallway adjacent to elevator	High Left	WF-02282022-009737	1/26/2023	FT-FY23-01102023-009737-A	<1	FT-FY23-01102023-009737-B	<1
WS- 009738	2/28/2022	2/28/2023	2	Cooler	In hallway adjacent to elevator	Low Right	WF-02282022-009738	1/26/2023	FT-FY23-01102023-009738-A	<1	FT-FY23-01102023-009738-B	<1
WS- 009739	2/28/2022	2/28/2023	2	Break Room	In staff lounge kitchen		WF-02282022-009739	1/26/2023	FT-FY23-01102023-009739-A	<1	FT-FY23-01102023-009739-B	<1
WS- 009760	2/28/2022	2/28/2023	3	Cooler	In hallway adjacent to elevator	High Right	WF-02282022-009760	1/26/2023	FT-FY23-01102023-009760-A	<1	FT-FY23-01102023-009760-B	<1
WS- 009761	2/28/2022	2/28/2023	3	Cooler	In hallway adjacent to elevator	Low Left	WF-02282022-009761	1/26/2023	FT-FY23-01102023-009761-A	<1	FT-FY23-01102023-009761-B	<1
WS- 009779	2/28/2022	2/28/2023	3	Break Room	In workroom A325		WF-02282022-009779	1/26/2023	FT-FY23-01102023-009779-A	<1	FT-FY23-01102023-009779-B	<1
WS- 009780	2/28/2022	2/28/2023	2	Break Room	In workroom A227		WF-02282022-009780	1/26/2023	FT-FY23-01102023-009780-A	<1	FT-FY23-01102023-009780-B	<1
WS- 009781	2/28/2022	2/28/2023	3	Break Room	In workroom A327		WF-02282022-009781	1/26/2023	FT-FY23-01102023-009781-A	<1	FT-FY23-01102023-009781-B	<1
WS- 009782	2/28/2022	2/28/2023	2	Break Room	In workroom A226		WF-02282022-009782	1/26/2023	FT-FY23-01102023-009782-A	<1	FT-FY23-01102023-009782-B	<1
WS- 009786	2/28/2022	2/28/2023	1	Health Suite	In health suite B112		WF-02282022-009786	1/26/2023	FT-FY23-01102023-009786-A	<1	FT-FY23-01102023-009786-B	<1
WS- 009787	2/28/2022	2/28/2023	1	Break Room	In workroom B116		WF-02282022-009787	1/26/2023	FT-FY23-01102023-009787-A	<1	FT-FY23-01102023-009787-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009706	2/15/2022	2/15/2023	1	Food Prep Sink	In kitchen across from room D114	WF-02152022-009706	1/26/2023	FT-FY23-01102023-009706-A	<1	FT-FY23-01102023-009706-B	<1